

51/3 Firrhill Drive EDINBURGH EH13 9EU 06/05/2025

- 1. Single Survey
- 2. Energy Report
- 3. Property Questionnaire

### survey report on:

Property address	1F1, 51 Firrhill Drive, Firrhill, Edinburgh, EH13 9EU
Customer	Miss Hinchcliffe
Customer address	
Prepared by	Graham & Sibbald
Date of inspection	2nd May 2025

### **GRAHAM + SIBBALD**

### **PART 1 - GENERAL**

### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

Х

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether
  or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.<sup>2</sup>

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

<sup>&</sup>lt;sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;

- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

### PART 2 - DESCRIPTION OF THE REPORT

### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The property comprises a first floor flat within a three storey block.
Accommodation	FIRST FLOOR - Entrance Vestibule, Hall, Livingroom/ Dining, Kitchen, Two Bedrooms and Bathroom
Gross internal floor area (m²)	66m² or thereby
Neighbourhood and location	The property is located within an established residential area with surrounding properties being comparable in terms of age, type and character lying to the south of Edinburgh City centre. Local facilities and amenities are readily available.
Age	circa 1960
Weather	Dry and clear
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.  Chimney stacks are of rendered masonry construction.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.  Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	The roof is of traditional pitched timber construction overlaid in tiles.  No access to the roof space afforded.

Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	Gutters and downpipes are of PVC construction discharging into the mains drainage system.
Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are of non-traditional no fines concrete construction, having been externally clad in insulation and rerendered.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows throughout are of uPVC double glazed type.
	The front access door is of timber.
External decorations	Visually inspected.
	Visually inspected.
Conservatories / porches	None.
Communal areas	Circulation areas visually inspected
Communal areas	Circulation areas visually inspected.
	There is a common entrance, stair and landing with secure entry phone system.
Garages and permanent outbuildings	None.
Outside areas and boundaries	Visually inspected.
	The property benefits from an area of communal garden ground to the rear elevation.
	The boundaries appear to be defined by timber/metal fencing as well as brick walling pointed externally.

Visually inspected from floor level.
The ceilings are of plastered masonry/concrete construction.
Visually inspected from floor level.
Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
The internal walls are of plastered masonry.
Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
The flooring appears to be of solid construction with a floating timber overlay with fitted floor coverings throughout.
Built-in cupboards were looked into but no stored items were moved.
Kitchen units were visually inspected excluding appliances.
The internal doors, skirting, etc. are of timber construction.
The kitchen contains a range of wall and base mounted storage units with worktop surfaces.
Visually inspected.
No testing of the flues or fittings was carried out.  Blocked/sealed and we assume adequately vented.
No testing of the flues or fittings was carried out.
No testing of the flues or fittings was carried out.
No testing of the flues or fittings was carried out.  Blocked/sealed and we assume adequately vented.

Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.  Mains supply with fuse box located within the entrance vestibule.
Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.  Mains supply.
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks,
Trator, pramong, bann com mange	cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Mains supply.
	Internal plumbing where seen appears to be of PVC and copper.
	The sanitary arrangements comprise of a three piece bathroom suite.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	Heating and hot water is by way of a modern gas fired combination boiler located within one of the kitchen cupboards.
Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	Assumed to be connected to the main public sewer.
Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	Visually inspected.

#### Any additional limits to inspection

#### For flats / maisonettes

Only the subject flat and internal communal areas giving access to the flat were inspected.

If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.

The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

It should be appreciated that concealed areas beneath and around baths and shower trays could not be inspected. Water spillage in these areas can result in dampness/decay and no comment can be made on inaccessible areas.

New smoke alarm standards were introduced in Scotland in February 2022 and it is likely that some properties may require additional works to meet these standards. In instances where alarms are in place, no tests whatsoever have been carried out and we cannot confirm if the system complies with the most recent regulations. Any potential purchaser should satisfy themselves as to whether the current system meets with regulations or otherwise.

The property was fully furnished at the time of our inspection and the services were not tested.

No access was obtained to the roof void or roof eaves areas.

A restricted inspection was possible only of the roof and chimneys from ground level.

The property was fully furnished at the time of our inspection and the services were not tested.

It is outwith the scope of this inspection to determine whether or not asbestos based products are present within the property. Asbestos was widely used in the building industry until around 1999, when it became a banned substance. If you have any concerns you should engage the services of a qualified asbestos surveyor.


Restricted inspection in cupboards due to storage items.

No inspection for Japanese Knotweed was carried out and unless otherwise stated for the purpose of this report, it is assumed that there is no Japanese Knotweed within the boundaries of the property or neighbouring properties.

Our inspection was restricted to the exposed and accessible surface fabric.

It should be appreciated that the Home Report inspection is a nondisruptive visual inspection of the property as at the date of inspection and that we are unable to inspect parts of the property which are concealed or covered by floor coverings or contents in place at that time. Once vacant, defects may be apparent that could not be detected during our survey. Changing weather conditions can also affect aspects of the property which would not be apparent at the time of inspection.

### Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2) Coping stone
- 3) Chimney head
- 4 Flashing
- (5) Ridge ventilation
- 6) Ridge board
- 7) Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- 10 Dormer flashing
- 11) Dormer cheeks
- 12) Sarking
- (13) Roof felt
- (14) Trusses
- (15) Collar
- (16) Insulation
- 17) Parapet gutter
- (18) Eaves guttering
- 19) Rainwater downpipe
- 20) Verge boards/skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- (25) Window pointing
  - 6) Window sills
- 27) Rendering
- (28) Brickwork / pointing
- 29 Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33 Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- 39) Water tank
- 40 Hot water tank

### 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	At the time of our inspection there was no evidence of significant structural movement noted to affect the property within the limits of our inspection.

Dampness, rot and infestation	
Repair category	1
Notes	There was no evidence found of significant dampness, rot or infestation within those areas of the property available for inspection.

Chimney stacks	
Repair category	2
Notes	Worn/defective render evident. Ongoing maintenance and repair should be anticipated.

Roofing including roof space	
Repair category	2
Notes	The roof was noted to be in fair order commensurate with the age and type of property although some ongoing maintenance and repairs are likely to be required with particular respect to misaligned tiles, defective ridge pointing as well as moss growth on the surfaces.  The roof covering is now of an age where ongoing repair and regular maintenance will be required and it would be prudent to seek the advice of a roofing contractor to comment on its current condition and expected lifespan.

Rainwater fittings	
Repair category	1
Notes	At the time of our inspection there was no evidence of damp staining/ water staining on wall surfaces which would indicate leakage. It should be noted that it was not raining at the time of our inspection.

Main walls	
Repair category	2
Notes	Areas of cracked render as well as weathering to base course level. Ongoing maintenance/repairs should be anticipated.

Windows, external doors and joinery	
Repair category	2
Notes	Due to the age of the windows, a degree of ongoing maintenance/repair should be anticipated. (Some loose handles evident).
	Windows can be problematic and over time the operation of the windows can be affected and opening mechanisms damaged. It is therefore likely that maintenance/ repair will be required as part of an ongoing maintenance programme.
	Double glazed windows may be prone to misting/interstitial condensation which can be more evident and can change in certain temperatures/weather conditions.

External decorations	
Repair category	1
Notes	The external decorations are generally in fair order. Regular repainting will be required if these areas are to be maintained in satisfactory condition.

Conservatories/porches	
Repair category	-
Notes	Not applicable.

Communal areas	
Repair category	2
Notes	Communal areas serving the property require repair and redecoration.

Communal areas	
Repair category	2
Notes	Weathered timbers evident throughout the common stair to windows and access doors.

Garages and permanent outbuildings	
Repair category	-
Notes	Not applicable.

Outside areas and boundaries	
Repair category	2
Notes	Outside areas will require ongoing repairs and maintenance.

Ceilings	
Repair category	1
Notes	Within the limits of our inspection these generally appeared in fair condition consistent with age. During redecoration some plaster filling/repair may be required.

Internal walls	
Repair category	1
Notes	Within the limits of our inspection these generally appeared in fair condition consistent with age. During redecoration some plaster filling/ repair may be required.

Floors including sub-floors	
Repair category	1
Notes	The flooring is generally level and firm to tread.

Internal joinery and kitchen fittings	
Repair category	1
Notes	The internal joinery is generally in keeping with the age and type of property and appeared in fair condition consistent with age.
	The kitchen fittings are generally in adequate condition for their age and type.

Chimney breasts and fireplaces	
Repair category	1
Notes	All original fireplaces have been removed/ blocked and we assume adequately vented.

Internal decorations	
Repair category	1
Notes	The property is generally in fresh decoration throughout.

Cellars	
Repair category	-
Notes	Not applicable.

Electricity	
Repair category	2
Notes	The electrical system is on mixed lines and as such we recommend that it be checked and upgraded as necessary by an NICEIC/ SELECT registered Electrical Contractor.

Gas	
Repair category	1
Notes	In the interest of safety all gas appliances should be checked by a Gas Safe Registered Engineer.

Water, plumbing and bathroom fittings	
Repair category	1
Notes	The plumbing and fittings appear of copper/ pvc piping where seen and appeared in serviceable condition but was not tested.
	The sanitary fittings appeared in fair order consistent with age.

Heating and hot water	
Repair category	1
Notes	A gas fired central heating system has been installed. This will require ongoing and regular servicing.
	We have been advised that the boiler was installed circa 2024 and under cover of guarantee. The details of this should be sought prior to purchase.

Drainage	
Repair category	1
Notes	The property is thought to be connected to a main sewer. There was no surface evidence to suggest the system is choked or leaking.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	2
Roofing including roof space	2
Rainwater fittings	1
Main walls	2
Windows, external doors and joinery	2
External decorations	1
Conservatories/porches	-
Communal areas	2
Garages and permanent outbuildings	-
Outside areas and boundaries	2
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	2
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

### **Category 3**

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

### 3. Accessibility information

### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	First floor
2. Are there three steps or fewer to a main entrance door of the property?	Yes No X
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes X No
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

### Matters for a solicitor or licensed conveyancer

We are unaware of any adverse planning proposals affecting the subjects although this should be confirmed by obtaining a Property Enquiry Certificate. Absolute ownership assumed. We are unaware of any easements, servitudes or rights of way which may adversely affect the property. This point should be confirmed by reference to the Title Deeds.

We assume that the carriageways etc., ex adverso the subjects are the responsibility of the Local Authority. It is also assumed that any new access roads, footpaths etc., will be private and will be brought up to adoption standards and liability thereafter will be shared according to use.

The subjects form part of a block of flats and it has been assumed that maintenance/ repair costs of the common parts of the building and external grounds will be shared on an equitable basis with the adjoining proprietors. It is therefore assumed that the costs of repairs detailed within this report which relate to these areas should be apportioned accordingly, although exact liability should be confirmed.

It is recommended that where repairs, defects or maintenance items have been identified, particularly categorised as a 2 or 3, interested parties make appropriate enquiries in order to satisfy themselves of potential costs and the extent of the works required prior to submitting a legal offer to purchase.

The main walls are of non-traditional no fines concrete construction.

It is assumed any documentation in relation to the external insulation and rerendering is available for transfer.

Estimated reinstatement cost for insurance purposes		
£180,000 (One Hundred and Eighty Thousand Pounds Sterling).		Sterling).
	Valuation and market comments	
	£155,000 (One Hundred and Fifty-Five Thousand Pou	nds Sterling).
	Signed Security	Print Code [503777 = 4004 ]
	Flectron	ically signed

Michael Gill

Report author

Company name	Graham & Sibbald
Address	40 Torphichen Street, Edinburgh, EH3 8JB
<u> </u>	
Date of report	6th May 2025

### **GRAHAM + SIBBALD**

Property Address			
Address Seller's Name Date of Inspection	1F1, 51 Firrhill Drive, Firrhill, Edinburgh, EH13 9EU Miss Hinchcliffe 2nd May 2025		
<b>Property Details</b>			
Property Type	House Bungalow Chalet Purpose built maisonette  Coach Studio Converted maisonette X Purpose built flat  Converted flat Flat over non-residential use Other (specify in General Remarks)	(S)	
Property Style	□ Detached       □ Semi detached       □ Mid terrace       □ End terrace         □ Back to back       □ High rise block       X Low rise block       □ Other (specify in General Remarks)	(s)	
Does the surveyor be e.g. local authority, m	lieve that the property was built for the public sector, X Yes No ilitary, police?		
Flats/Maisonettes onl			
Approximate Year of	No. of units in block 6  Construction 1960		
Tenure			
Absolute Ownership	Leasehold Ground rent £ Unexpired years		
Accommodation			
Number of Rooms	1     Living room(s)     2     Bedroom(s)     1     Kitchen(s)       1     Bathroom(s)     1     WC(s)     0     Other (Specify in General remarks)		
Gross Floor Area (excluding garages and outbuildings)  Residential Element (greater than 40%) X Yes No			
Garage / Parking /	Outbuildings		
Single garage Available on site?	☐ Double garage       ☐ Parking space         ☐ Yes       ☐ No             X       No garage / garage space / parking space         X       No garage / garage space / parking space	Ð	
Permanent outbuildings:			
None.			

Construction									
Walls	Brick	Stone		Concrete	Timb	er frame			
	Solid	Cavity		Steel frame		rete block	X Oth	ner (specify in Ge	neral Remarks)
Roof	X Tile	Slate		sphalt	Felt			(-)	,
	Lead	Zinc		Artificial slate		glass fibre	Oth	ner (specify in Ge	neral Remarks)
Special Risks									
Has the property s	uffered structu	ıral moveme	ent?					Yes	X No
If Yes, is this recen	nt or progressi	ve?						Yes	No
Is there evidence, I immediate vicinity?		son to antic	ipate sub	sidence, h	neave, la	andslip (	or flood in t	he Yes	No
If Yes to any of the	above, provid	de details in	General	Remarks.					
Service Connect	tion								
Based on visual ins of the supply in Ge			ces appe	ar to be n	on-main	s, pleas	e comment	t on the type a	nd location
Drainage	X Mains	Private	None			Water	X Mains	Private	None
Electricity	X Mains	Private	None			Gas	X Mains	Private	None
Central Heating	X Yes [	Partial	None						
Brief description of	Central Heat	ng:							
Gas fired boiler to	o radiators.								
Site									
Apparent legal issu	ios to bo vorif	ind by the c	onvovana	or Plance	n provid	o a briof	doscription	n in Conoral E	lomarke
Rights of way	Shared drive	-		e or other an	-			nared service con	
Agricultural land inc				ned boundar		п зорагак		ther (specify in G	
	iddod Willi propor			iod bouridar				inor (opcony in oc	onoral Homanio,
Location									
Residential suburb	X Resi	dential within to	own / city	Mixed	residentia	I / comme	rcial Ma	ainly commercial	
Commuter village	Rem	ote village		Solate	d rural pro	operty	Ot	her (specify in Ge	eneral Remarks)
Planning Issues									
Has the property be	een extended	/ converted	/ altered	? Ye	s X No	)			
If Yes provide deta	ils in General	Remarks.							
Roads									
X Made up road	Unmade road	Partly	completed	new road	P€	edestrian a	access only	Adopted	Unadopted

General Remarks
The property is located within an established residential area with surrounding properties being comparable in terms of age, type and character lying to the south of Edinburgh City centre. Local facilities and amenities are readily available.
The main walls are of non-traditional no fines concrete construction, having been externally clad in insulation and re-rendered.
The general condition of the property appears consistent with its age and type of construction, however an ongoing maintenance routine to the external fabric should be anticipated.
Essential Repairs
Estimated cost of essential repairs £ Retention recommended? Yes No Amount £

Comment on Mortgagea	bility			
Valuations				
Valuations				
Market value in present con	ndition	£ 155,000		
Market value on completion	of essential repairs	£		
Insurance reinstatement value				
(to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)				
Is a reinspection necessary?				
Buy To Let Cases				
What is the reasonable rand	ge of monthly rental income for the property assuming a letting on a 6	£		
month Short Assured Tenai		~		
Is the property in an area w	here there is a steady demand for rented accommodation of this type?	Yes No		
Declaration				
Signed	Security Print Code [503777 = 4004 ] Electronically signed by:-			
Surveyor's name	Michael Gill			
Professional qualifications	MRICS			
Company name	Graham & Sibbald			
Address	ress 40 Torphichen Street, Edinburgh, EH3 8JB			
Telephone	0131 225 1559			
Fax				
Report date	6th May 2025			

### **Energy Performance Certificate (EPC)**

**Dwellings** 

### **Scotland**

#### 1F1, 51 FIRRHILL DRIVE, FIRRHILL, EDINBURGH, EH13 9EU

Dwelling type:Mid-floor flatDate of assessment:02 May 2025Date of certificate:02 May 2025

**Total floor area:** 66 m<sup>2</sup>

Primary Energy Indicator: 167 kWh/m²/year

Reference number: 0322-1002-0205-0615-1204
Type of assessment: RdSAP, existing dwelling

Approved Organisation: Elmhurst

**Main heating and fuel:** Boiler and radiators, mains

gas


#### You can use this document to:

Compare current ratings of properties to see which are more energy efficient and environmentally friendly

### Estimated energy costs for your home for 3 years\*

£2,037

 $^st$  based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band C (78)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



### **Environmental Impact (CO<sub>2</sub>) Rating**

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$  emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (79)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

### Top actions you can take to save money and make your home more efficient

There are currently no improvement measures recommended for your home.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	System built, with external insulation	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Roof	(another dwelling above)	_	_
Floor	(another dwelling below)	_	_
Windows	Fully double glazed	***	<b>★★★</b> ☆☆
Main heating	Boiler and radiators, mains gas	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Main heating controls	Programmer, room thermostat and TRVs	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Secondary heating	None	_	_
Hot water	From main system	****	<b>★★★★</b> ☆
Lighting	Low energy lighting in all fixed outlets	****	****

### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 29 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 1.9 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

### Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings	
Heating	£1,395 over 3 years	£1,395 over 3 years		
Hot water	£420 over 3 years	£420 over 3 years	<b>N</b> 1 ( P 11	
Lighting	£222 over 3 years	£222 over 3 years	Not applicable	
Totals	£2,037	£2,037		

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

### **Recommendations for improvement**

None

### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

### Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	4,554	N/A	N/A	N/A
Water heating (kWh per year)	1,948			_

### **About this document**

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:
Assessor membership number:
Company name/trading name:
Address:

Mr. Michael Gill
EES/023864
Graham & Sibbald
40 Torphichen Street

Edinburgh EH3 8JB

Phone number: 0131 225 1559
Email address: edinburgh@g-s.co.uk
Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

# **Property Questionnaire**

Property Address	51/3 Firrhill Drive
	EDINBURGH
	EH13 9EU

Seller(s)	Ms Sydney Hinchcliffe
-----------	-----------------------

Completion date of property questionnaire	05/05/2025
---	------------

1	Length of ownership  How long have you owned the property?  2.5 years
2	Council tax Which Council Tax band is your property in? B
3	Parking   What are the arrangements for parking at your property?   (Please tick all that apply)   Garage □   Allocated parking space □   Driveway □   Shared parking □   On street ☑   Resident permit □   Metered parking □   Other (please specify)
4	Conservation area Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)? No
5	<b>Listed buildings</b> Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)? No
<b>6</b> a.(i)	Alterations/additions/extensions  During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?  No  If you have answered yes, please describe below the changes which you have made:
(ii)	Did you obtain planning permission, building warrant, completion certificate and other consents for this work?
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.  If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:

b. Have you had replacement windows, doors, patio doors or double glazing installed in your property?

No

- If you have answered yes, please answer the three questions below:
- (i) Were the replacements the same shape and type as the ones you replaced?
- (ii) Did this work involve any changes to the window or door openings?
- (iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):

Please give any guarantees which you received for this work to your solicitor or estate agent.

### 7 Central heating

a. Is there a central heating system in your property?

(Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).

Yes

If you have answered yes or partial — what kind of central heating is there?

(Examples: gas-fired, solid fuel, electric storage heating, gas warm air).

Gas

If you have answered yes, please answer the three questions below:

- (i) When was your central heating system or partial central heating system installed? 14 June 2024
- (ii) Do you have a maintenance contract for the central heating system?

Yes

If you have answered yes, please give details of the company with which you have a maintenance contract:

Celsius Plumbing and Heating

(iii) When was your maintenance agreement last renewed?

(Please provide the month and year).

06/2024

### 8 Energy Performance Certificate

Does your property have an Energy Performance Certificate which is less than 10 years old?

Yes

### 9 Issues that may have affected your property

a. Has there been any storm, flood, fire or other structural damage to your property while you have owned it?

No

If you have answered yes, is the damage the subject of any outstanding insurance claim?

b. Are you aware of the existence of asbestos in your property?

No

If you have answered yes, please give details:

### 10 Services

Please tick which services are connected to your property and give details of the supplier:

**Connected Supplier** Services Gas or liquid petroleum gas  $\overline{\mathbf{V}}$ British Gas Water mains or private water supply  $\overline{\mathbf{Q}}$ Scottish Water  $\overline{\mathbf{A}}$ Electricity British Gas Mains drainage  $\overline{\mathsf{V}}$ Scottish Water Telephone Cable TV or satellite  $\overline{\mathbf{V}}$ Sky Broadband  $\overline{\mathsf{V}}$ Sky

b. Is there a septic tank system at your property?

No

- (i) Do you have appropriate consents for the discharge from your septic tank?
- (ii) Do you have a maintenance contract for your septic tank?

If you have answered yes, please give details of the company with which you have a maintenance contract:

### 11 Responsibilities for shared or common areas

a. Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?

Yes

If you have answered yes, please give details:

Garder

b. Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?

Yes

If you have answered yes, please give details:

Roof, Stairwell

c. Has there been any major repair or replacement of any part of the roof during the time you have owned the property?

Yes

d. Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries?

Yes

If you have answered yes, please give details:

Maintain Garden Boundaries

e. As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?

Yes

If you have answered yes, please give details:

Maintain Garden Boundaries

f. As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)

No

If you have answered yes, please give details:

### 12 Charges associated with your property

a. Is there a factor or property manager for your property?

b. Is there a common buildings insurance policy?

No

If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?

c. Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.

### 13 Specialist works

a. As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?

No

If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.

b. As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?

No

If you have answered yes, please give details:

c. If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?

If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate., these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.

Guarantees are held by:

### 14 Guarantees

- a. Are there any guarantees or warranties for any of the following:
- (i) Electrical work

Don't know

(ii) Roofing

No

(iii) Central heating

Yes

(iv) National House Building Council (NHBC)

No

(v) Damp course

No

(vi) Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)

Yes

- b. <u>If you have answered 'yes'</u> or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):
- (i) Electrical work
- (ii) Roofing
- (iii) Central heating

Celcius Plumbing Warantee

- (iv) National House Building Council (NHBC)
- (v) Damp course
- (vi) Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)

Cavity wall insulation and harling carried out by changeworks august 2018

c. Are there any outstanding claims under any of the guarantees listed above?

No

If you have answered yes, please give details:

### 15 Boundaries

So far as your are aware, has any boundary of your property been moved in the last 10 years?

No

If you have answered yes, please give details:

### 16 Notices that affect your property

In the past three years have you ever received a notice:

- a. advising that the owner of a neighbouring property has made a planning application?
   No
- b. that affects your property in some other way?
- c. that requires you to do any maintenance, repairs or improvements to your property?

If you have answered yes to any of a–c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.