

SELLER'S DISCLOSURE NOTICE

©Texas Association of REALTORS®, Inc. 2023

Section 5.008, Property Code requires a seller of residential property of not more than one dwelling unit to deliver a Seller's Disclosure Notice to a buyer on or before the effective date of a contract. This form complies with and contains additional disclosures which exceed the minimum disclosures required by the Code.

							omp	lies	with	n a	and contains additional disclosure)S W	nıcr	1
PR	OP	ER	ΤΥ	ΑT	99	0 Harmony Circle,	Ne	va	da,	T	exas 75173			
D B ISH THE	YS IT(EL O (AGI	LEI DB1 EN	R AN TAIN T.	ND I . I	S NOT A SUBSTITUTE IS NOT A WARI	JTE RAI ed (E F NT` (by	OR Y O Sel	A F	NY INSPECTIONS OR WARF ANY KIND BY SELLER, SI r), how long since Seller has o	RAN ELLI	TIE ER' upie	S 'S
						(app	orox	kim	ate	d	ate) $\;\;\square$ Never occupied the I	⊃rop	pert	y.
												onve	ey.	
Υ	N	U		Iten	1		Υ	N	U		Item	Υ	N	ι
	✓			Nat	ıral	Gas Lines		✓			Pump: ☐ sump ☐ grinder		✓	
	✓			Fue	l Ga	as Piping:		✓			Rain Gutters	✓		
√				-Bla	ck I	ron Pipe		✓			Range/Stove	✓		
√				-Co	ppe	r		. /			Roof/Attic Vents	✓		
✓					_			✓			Sauna		✓	
√				Hot Tub				✓			Smoke Detector	√		
	✓			Intercom System		m System		✓			Smoke Detector – Hearing Impaired		~	
✓				Microwave		✓				Spa		✓		
✓				Outdoor Grill		r Grill		✓			Trash Compactor		✓	_
✓				Patio/Decking				/			TV Antenna		✓	
	✓			<u> </u>			✓				Washer/Dryer Hookup	√		
	√			Poo		<u> </u>	√				Window Screens	√		
	√			Poo	I Ec	quipment	√				Public Sewer System		√	_
	~			Pool Maint. Accessories				✓			,			
	✓			Poo	ΙHε	eater	✓							
			Y	N	U									
			✓			_	3	nuı	mbe	r	of units: 2			
				✓										
				✓										
Attic Fan(s)			V.	1		if yes, describe:								
Central Heat Other Heat			√				•	nui	mpe	r	of units: 2			
			,		√									
			<u> </u>					<u>. </u>	7 m					
			'	_							CK 🗆 Otilei.			
			×	1										
			√	-										
Satellite Dish & Controls				,										
	PRISCLED BISH THE not	PROP SCLOSD BY SISH TO FHER A not occurrently habitablish	PROPER SCLOSUF D BY SEL ISH TO C THER AGI not occup erty has tl stablish the Y N U V V V V V V V V	PROPERTY SCLOSURE OF BY SELLER ISH TO OBTOTION TO OCCUPYING THE PROPERTY ISH TO	PROPERTY AT SCLOSURE OF SO BY SELLER AN ISH TO OBTAIN THER AGENT. Inot occupying the stablish the items to sta	PROPERTY AT 99 SCLOSURE OF SELD BY SELLER AND I ISH TO OBTAIN. ITHER AGENT. Inot occupying the protection of the items to be i	PROPERTY AT 990 Harmony Circle, SCLOSURE OF SELLER'S KNOWLEDG BY SELLER AND IS NOT A SUBSTITUBLY TO OBTAIN. IT IS NOT A WARRET AGENT. not occupying the property. If unoccupies (appropriate the items marked below: (Mastablish the items to be conveyed. The control of the items to be	PROPERTY AT 990 Harmony Circle, New SCLOSURE OF SELLER'S KNOWLEDGE DBY SELLER AND IS NOT A SUBSTITUTE ISH TO OBTAIN. IT IS NOT A WARRAITHER AGENT. not occupying the property. If unoccupied (approximate) and the items to be conveyed. The contract of the items to be conveyed. The co	PROPERTY AT 990 Harmony Circle, Neval SCLOSURE OF SELLER'S KNOWLEDGE OF DBY SELLER AND IS NOT A SUBSTITUTE FISH TO OBTAIN. IT IS NOT A WARRANT'S HER AGENT. not occupying the property. If unoccupied (by (approxim) (appro	PROPERTY AT 990 Harmony Circle, Nevada, SCLOSURE OF SELLER'S KNOWLEDGE OF THID BY SELLER AND IS NOT A SUBSTITUTE FOR DESTRUCTION OBTAIN. IT IS NOT A WARRANTY OF THER AGENT. In the contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the stabilish the items to be conveyed. The contract will determine the convextence the stabilish the items to be conveyed. The contract will	PROPERTY AT 990 Harmony Circle, Nevada, To By Seller AND IS NOT A SUBSTITUTE FOR A ISH TO OBTAIN. IT IS NOT A WARRANTY OF THER AGENT. The not occupying the property. If unoccupied (by Selle (approximate diapproximate diapprox	PROPERTY AT 990 Harmony Circle, Nevada, Texas 75173	PROPERTY AT	PROPERTY AT 990 Harmony Circle, Nevada, Texas 75173 SCLOSURE OF SELLER'S KNOWLEDGE OF THE CONDITION OF THE PROPERTY AD BY SELLER AND IS NOT A SUBSTITUTE FOR ANY INSPECTIONS OR WARRANTIESH TO OBTAIN. IT IS NOT A WARRANTY OF ANY KIND BY SELLER, SELLER' HER AGENT. not occupying the property. If unoccupied (by Seller), how long since Seller has occupied (approximate date) Never occupied the Propert (approximate

SI ILERS SHELD	Prepared	with	Sellers	Shield
-------------------	----------	------	---------	--------

(TXR-1406) 07-10-23 Initiated By: Buyer: , and Seller: $\mathcal{E} \mathcal{K} \mathcal{H}$, $\mathcal{K} \mathcal{M} \mathcal{M}$ Page 1 of 7

If the answer to any of the items in Section 2 is yes, explain (attach additional sheets if necessary):

Section 3. Are you (Seller) aware of any of the following conditions? (Mark Yes (Y) if you are aware and No (N) if you are not aware.)

Condition	Υ	N
Aluminum Wiring		✓
Asbestos Components		✓
Diseased Trees: oak wilt		✓
Endangered Species/Habitat on Property		✓
Fault Lines		✓
Hazardous or Toxic Waste		✓
Improper Drainage		✓
Intermittent or Weather Springs		✓
Landfill		✓
Lead-Based Paint or Lead-Based Pt. Hazards		✓

Condition	Υ	N
Radon Gas		✓
Settling		✓
Soil Movement		✓
Subsurface Structure or Pits		✓
Underground Storage Tanks		✓
Unplatted Easements		✓
Unrecorded Easements		✓
Urea-formaldehyde Insulation		✓
Water Damage Not Due to a Flood Event		✓
Wetlands on Property		✓



(TXR-1406) 07-10-23 Initiated By: Buyer: Page 2 of 7 and Seller: $\mathcal{E}KH$, KMM

Concerning the Property at 990 Harmony Circle, Nevada, Texas 75173 Wood Rot Encroachments onto the Property ✓ Improvements encroaching on others' property √ Active infestation of termites or other wood destroying insects (WDI) Located in Historic District Previous treatment for termites or WDI ✓ ✓ Previous termite or WDI damage repaired Historic Property Designation ✓ ✓ **Previous Foundation Repairs** ✓ **Previous Fires** √ Previous Roof Repairs Termite or WDI damage needing repair ✓ ✓ Single Blockable Main Drain in Pool/Hot Previous Other Structural Repairs ✓ √ Tub/Spa* Previous Use of Premises for Manufacture ✓ of Methamphetamine If the answer to any of the items in Section 3 is yes, explain (attach additional sheets if necessary): *A single blockable main drain may cause a suction entrapment hazard for an individual. Section 4. Are you (Seller) aware of any item, equipment, or system in or on the Property that is in need of repair, which has not been previously disclosed in this notice? □ yes ☑ no If yes, explain (attach additional sheets if necessary): Section 5. Are you (Seller) aware of any of the following conditions?* (Mark Yes (Y) if you are aware and check wholly or partly as applicable. Mark No (N) if you are not aware.) Υ Ν \Box $\sqrt{}$ Present flood insurance coverage. Previous flooding due to a failure or breach of a reservoir or a controlled or emergency release of $\sqrt{}$ water from a reservoir. Previous flooding due to a natural flood event. $\sqrt{}$ Previous water penetration into a structure on the Property due to a natural flood. $\sqrt{}$ \Box Located Umholly partly in a 100-year floodplain (Special Flood Hazard Area-Zone A, V, A99, AE, $\sqrt{}$ AO, AH, VE, or AR). $\sqrt{}$ Located □ wholly □ partly in a 500-year floodplain (Moderate Flood Hazard Area-Zone X (shaded)). П $\sqrt{}$ Located □ wholly □ partly in a floodway. $\sqrt{}$ Located \square wholly \square partly in a flood pool. $\sqrt{}$ Located □ wholly □ partly in a reservoir. If the answer to any of the above is yes, explain (attach additional sheets as necessary):



(TXR-1406) 07-10-23 Initiated By: Buyer: , and Seller: $\mathcal{E}\mathcal{KH}$, \mathcal{KMM} Page 3 of 7

*If I	Buyer is concerned about these matters, Buyer may consult Information About Flood Hazards (TXR 1414).
For	purposes of this notice:
whic	D-year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a special flood hazard area h is designated as Zone A, V, A99, AE, AO, AH, VE, or AR on the map; (B) has a one percent annual chance of flooding, which is didered to be a high risk of flooding; and (C) may include a regulatory floodway, flood pool, or reservoir.
whic	year floodplain" means any area of land that: (A) is identified on the flood insurance rate map as a moderate flood hazard area h is designated on the map as Zone X (shaded); and (B) has a two-tenths of one percent annual chance of flooding, which i didered to be a moderate risk of flooding.
	od pool" means the area adjacent to a reservoir that lies above the normal maximum operating level of the reservoir and that i ect to controlled inundation under the management of the United States Army Corps of Engineers.
	od insurance rate map" means the most recent flood hazard map published by the Federal Emergency Management Agenc er the National Flood Insurance Act of 1968 (42 U.S.C. Section 4001 et seq.).
river	odway" means an area that is identified on the flood insurance rate map as a regulatory floodway, which includes the channel of or other watercourse and the adjacent land areas that must be reserved for the discharge of a base flood, also referred to as year flood, without cumulatively increasing the water surface elevation more than a designated height.
"Res	servoir" means a water impoundment project operated by the United States Army Corps of Engineers that is intended to retai or or delay the runoff of water in a designated surface area of land.
	nal sheets as necessary):
*Hor	nes in high risk flood zones with mortgages from federally regulated or insured landers are required to have flood insurance. Eve
where low rection	n not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, moderate risk, ar risk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the structure(s). 1 7. Have you (Seller) ever received assistance from FEMA or the U.S. Small Busines
when low rection meces	n 7. Have you (Seller) ever received assistance from FEMA or the U.S. Small Businessistration (SBA) for flood damage to the Property? ☐ yes ☑ no If yes, explain (attach additional sheet essary): 18. Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) are not aware.)
when low rection neces	not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, moderate risk, an risk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the structure(s). 7. Have you (Seller) ever received assistance from FEMA or the U.S. Small Business stration (SBA) for flood damage to the Property? yes no If yes, explain (attach additional sheet essary): 8. Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) are not aware.) Room additions, structural modifications, or other alterations or repairs made without necessary permits, with unresolved permits, or not in compliance with building codes in effect at the time
ction ctior ctior	not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, moderate risk, an risk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the structure(s). 7. Have you (Seller) ever received assistance from FEMA or the U.S. Small Busines is stration (SBA) for flood damage to the Property? yes no If yes, explain (attach additional sheet researcy): 8. Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) are not aware.) Room additions, structural modifications, or other alterations or repairs made without necessary permits, with unresolved permits, or not in compliance with building codes in effect at the time Homeowners' associations or maintenance fees or assessments. If yes, complete the following:
ction ctior ctior	not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, moderate risk, an isk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the structure(s). 7. Have you (Seller) ever received assistance from FEMA or the U.S. Small Business istration (SBA) for flood damage to the Property? yes no If yes, explain (attach additional sheet essary): 8. Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) are not aware.) Room additions, structural modifications, or other alterations or repairs made without necessary permits, with unresolved permits, or not in compliance with building codes in effect at the time Homeowners' associations or maintenance fees or assessments. If yes, complete the following: Name of association:
ction ctior ctior	not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, moderate risk, an risk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the structure(s). 7. Have you (Seller) ever received assistance from FEMA or the U.S. Small Business stration (SBA) for flood damage to the Property? yes no If yes, explain (attach additional sheet essary): 8. Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) are not aware.) Room additions, structural modifications, or other alterations or repairs made without necessary permits, with unresolved permits, or not in compliance with building codes in effect at the time Homeowners' associations or maintenance fees or assessments. If yes, complete the following:
ction neces	not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, moderate risk, an isk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the structure(s). 7. Have you (Seller) ever received assistance from FEMA or the U.S. Small Busines istration (SBA) for flood damage to the Property? □ yes ☑ no If yes, explain (attach additional sheet essary): 8. Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) are not aware.) Room additions, structural modifications, or other alterations or repairs made without necessary permits, with unresolved permits, or not in compliance with building codes in effect at the time Homeowners' associations or maintenance fees or assessments. If yes, complete the following: Name of association: □ Phone: □ Phone: □ mandatory □ voluntary.
ction ction	not required, the Federal Emergency Management Agency (FEMA) encourages homeowners in high risk, moderate risk, an isk flood zones to purchase flood insurance that covers the structure(s) and the personal property within the structure(s). 7. Have you (Seller) ever received assistance from FEMA or the U.S. Small Busines istration (SBA) for flood damage to the Property? yes no If yes, explain (attach additional sheet essary): 8. Are you (Seller) aware of any of the following? (Mark Yes (Y) if you are aware. Mark No (N) are not aware.) Room additions, structural modifications, or other alterations or repairs made without necessary permits, with unresolved permits, or not in compliance with building codes in effect at the time Homeowners' associations or maintenance fees or assessments. If yes, complete the following: Name of association: Manager's Name: Phone:

(TXR-1406) 07-10-23 Initiated By: Buyer: _____ , ____ and Seller: ______ & _____ / ____ Page 4 of 7

Cor	ncernin	g the Prope	rty at <u>990 Harmon</u>	y Circle, Nevada, Texa	s 75173		
				such as pools, tennis complete the following:	ourts, walkways, or other)	co-owned in undivided	
	abla					describe	
	V		ces of violations of ne Property.	f deed restrictions or go	overnmental ordinances af	fecting the condition or	
	Ø	Any lawsuits or other legal proceedings directly or indirectly affecting the Property. (Includes, but is not limited to: divorce, foreclosure, heirship, bankruptcy, and taxes.)					
	V	Any death on the Property except for those deaths caused by: natural causes, suicide, or accident unrelated to the condition of the Property.					
	V	Any con	dition on the Proper	ty which materially affec	ts the health or safety of ar	n individual.	
	V	Any repairs or treatments, other than routine maintenance, made to the Property to remediate environmental hazards such as asbestos, radon, lead-based paint, urea-formaldehyde, or mold.					
	V			stem located on the Pro auxiliary water source.	perty that is larger than 50	0 gallons and that uses	
	V	The Property is located in a propane gas system service area owned by a propane distribution system retailer.					
	Ø	Any portion of the Property that is located in a groundwater conservation district or a subsidence district.					
If t	he an	swer to ar	ny of the items in Se	ection 8 is yes, explain (a	uttach additional sheets if n	ecessary):	
wh	o reg	jularly pr	ovide inspections	and who are either lic	ed any written inspection ensed as inspectors or o pies and complete the follo	otherwise permitted by	
	•	on Date	Туре	Name of Inspector		No. of Pages	
09-	11-20	24	PROPERTY INSPECTION REPOR	William Christopher Mu	ıllins	40	
No	ote: A	N buyer sh	-	•	a reflection of the current co spectors chosen by the bu		
Se	ection	10. Ched	ck any tax exempti	on(s) which you (Selle	r) currently claim for the	Property:	
	☑ Ho	mestead		☐ Senior Citizen	□ Disabled		
Pres	pared with S	iellers Shield					
VD 1	400\ 0	7 10 22	Initiated Dvs. Duv	or. and	Collors 0 at at	1 2 4 2 4 Dama 5 of 7	

(TXR-1406) 07-10-23 Initiated By: Buyer: , and Seller: £ K H , K M M Page 5 of 7

Concerning the Property at 990 Ha	rmony Circle, Nevada, 1	Гехаs 75173	
☐ Wildlife Management☐ Other:	□ Agricultural	□ Disabled Veteran □ Unknown	
Section 11. Have you (Seller) of any insurance provider?		mage, other than flood damage	e, to the Property with
	ment or award in a legal	for a claim for damage to the P proceeding) and not used the If yes, explain:	
	oter 766 of the Health an	detectors installed in accord nd Safety Code?* □ unknown ary):	
installed in accordance with the re	quirements of the building code source requirements. If you do	nily or two-family dwellings to have wo e in effect in the area in which the dwelli not know the building code requirement icial for more information.	ng is located, including
who will reside in the dwelling is he a licensed physician; and (3) with	earing-impaired; (2) the buyer g in 10 days after the effective d mpaired and specifies the loca	ring impaired if: (1) the buyer or a memb sives the seller written evidence of the he late, the buyer makes a written request tions for installation. The parties may a detectors to install.	earing impairment from for the seller to install
	(s), has instructed or influ	ce are true to the best of Seller's enced Seller to provide inaccura	
Edward K Hemphill	2025-08-31	Kristina Marie Malone	2025-08-31
Signature of Seller	Date	Signature of Seller	Date
Printed Name: Edward K Hem	phill	Printed Name: Kristina Mari	e Malone
ADDITIONAL NOTICES TO BU	YER:		
determine if registered sex offer	nders are located in certain For information concerni	a database that the public may in zip code areas. To search the ng past criminal activity in certain	database, visit

- (2) If the Property is located in a coastal area that is seaward of the Gulf Intracoastal Waterway or within 1,000 feet of the mean high tide bordering the Gulf of Mexico, the Property may be subject to the Open Beaches Act or the Dune Protection Act (Chapter 61 or 63, Natural Resources Code, respectively) and a beachfront construction certificate or dune protection permit may be required for repairs or improvements. Contact the local government with ordinance authority over construction adjacent to public beaches for more information.
- (3) If the Property is located in a seacoast territory of this state designated as a catastrophe area by the Commissioner of the Texas Department of Insurance, the Property may be subject to additional requirements

(TXR-1406) 07-10-23 Initiated By: Buyer: and Seller: Page 6 of 7 $\mathcal{E} \mathcal{K} \mathcal{H}$, $\mathcal{K} \mathcal{M} \mathcal{M}$

to obtain or continue windstorm and hail insurance. A certificate of compliance may be required for repairs or improvements to the Property. For more information, please review *Information Regarding Windstorm and Hail Insurance for Certain Properties* (TXR 2518) and contact the Texas Department of Insurance or the Texas Windstorm Insurance Association.

- (4) This Property may be located near a military installation and may be affected by high noise or air installation compatible use zones or other operations. Information relating to high noise and compatible use zones is available in the most recent Air Installation Compatible Use Zone Study or Joint Land Use Study prepared for a military installation and may be accessed on the Internet website of the military installation and of the county and any municipality in which the military installation is located.
- (5) If you are basing your offers on square footage, measurements, or boundaries, you should have those items independently measured to verify any reported information.
- (6) The following providers currently provide service to the Property:

Electric: TXU/Oncor	Phone #: (866) 278-4898
Sewer: Year Round Septic Services	Phone #: (469) 512-9149
Water: COPEVILLE SPECIAL UTILITY DISTRICT	Phone #: (972) 853-4630
Cable: na	Phone #:
Trash: Residential trash pickup from CARDS	Phone #: (877) 592-2737
Natural Gas: na	_ Phone #:
Phone Company: na	_ Phone #:
Propane: na	Phone #:
Internet:FRONTIER FIBER INTERNET	Phone #: (800) 917-7489

This Seller's Disclosure Notice was completed by Seller as of the date signed. The brokers have relied on this notice as true and correct and have no reason to believe it to be false or inaccurate. YOU ARE ENCOURAGED TO HAVE AN INSPECTOR OF YOUR CHOICE INSPECT THE PROPERTY.

The undersigned Buyer acknowledges receipt of the foregoing notice.

Signature of Buyer	Date	Signature of Buyer	Date
Printed Name:		Printed Name:	



(TXR-1406) 07-10-23 Initiated By: Buyer: , and Seller: $\mathcal{E}\mathcal{KH}$, \mathcal{KMM} Page 7 of 7



Residential & Commercial | Termite | Pools | Septic | Wells | New Construction **5000 Eldorado Parkway** 469) 438-8509 office

Suite #150-103 KisseeInspections.com **Frisco, TX 75033**

Info@kisseeinspections.com



Inspected By: William Christophen Mullins TREC #23852









PROPERTY INSPECTION REPORT FORM

Kristina Malone & Eddie Hemphill Name of Client	09/11/2024 Date of Inspection
990 Harmony Cir, Nevada, TX 75173 Address of Inspected Property	
William Christopher Mullins Name of Inspector	23852 TREC License #
Name of Sponsor (if applicable)	TREC License #

PURPOSE OF INSPECTION

A real estate inspection is a visual survey of a structure and a basic performance evaluation of the systems and components of a building. It provides information regarding the general condition of a residence at the time the inspection was conducted. *It is important* that you carefully read ALL of this information. Ask the inspector to clarify any items or comments that are unclear.

RESPONSIBILITY OF THE INSPECTOR

This inspection is governed by the Texas Real Estate Commission (TREC) Standards of Practice (SOPs), which dictates the minimum requirements for a real estate inspection.

The inspector IS required to:

- use this Property Inspection Report form for the inspection;
- inspect only those components and conditions that are present, visible, and accessible at the time of the inspection;
- indicate whether each item was inspected, not inspected, or not present;
- indicate an item as Deficient (D) if a condition exists that adversely and materially affects the performance of a system or component **OR** constitutes a hazard to life, limb or property as specified by the SOPs; and
- explain the inspector's findings in the corresponding section in the body of the report form.

The inspector IS NOT required to:

- identify all potential hazards;
- turn on decommissioned equipment, systems, utilities, or apply an open flame or light a pilot to operate any appliance;
- climb over obstacles, move furnishings or stored items;
- prioritize or emphasize the importance of one deficiency over another;
- provide follow-up services to verify that proper repairs have been made; or
- inspect system or component listed under the optional section of the SOPs (22 TAC 535.233).

RESPONSIBILITY OF THE CLIENT

While items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions, in the event that any further evaluations are needed, it is the responsibility of the client to obtain further evaluations and/or cost estimates from qualified service professionals regarding any items reported as Deficient (D). It is recommended that any further evaluations and/or cost estimates take place prior to the expiration of any contractual time limitations, such as option periods.

Please Note: Evaluations performed by service professionals in response to items reported as Deficient (D) on the report may lead to the discovery of additional deficiencies that were not present, visible, or accessible at the time of the inspection. Any repairs made after the date of the inspection may render information contained in this report obsolete or invalid.

REPORT LIMITATIONS

This report is provided for the benefit of the named client and is based on observations made by the named inspector on the date the inspection was performed (indicated above).

ONLY those items specifically noted as being inspected on the report were inspected.

This inspection IS NOT:

- a technically exhaustive inspection of the structure, its systems, or its components and may not reveal all deficiencies;
- an inspection to verify compliance with any building codes;
- an inspection to verify compliance with manufacturer's installation instructions for any system or component and DOES NOT imply insurability or warrantability of the structure or its components.

NOTICE CONCERNING HAZARDOUS CONDITIONS, DEFICIENCIES, AND CONTRACTUAL AGREEMENTS

Conditions may be present in your home that did not violate building codes or common practices in effect when the home was constructed but are considered hazardous by today's standards. Such conditions that were part of the home prior to the adoption of any current codes prohibiting them may not be required to be updated to meet current code requirements. However, if it can be reasonably determined that they are present at the time of the inspection, the potential for injury or property loss from these conditions is significant enough to require inspectors to report them as Deficient (D). Examples of such hazardous conditions include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices and arc-fault devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

Please Note: items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions. The decision to correct a hazard or any deficiency identified in an inspection report is left up to the parties to the contract for the sale or purchase of the home.

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

Report: The inspection report provided by Kissee Home Inspections LLC here after referred to as Kissee Inspections will contain the good faith opinions of the inspector concerning the observable need, if any, on the day of the inspection, for the repair, replacement, or further evaluation by experts of the items inspected. Unless, specifically stated, this report will not include and should not be read to indicated opinions as to the environmental conditions such as the presence of mold, radon or lead base paint, the presence of toxic or hazardous waste or substances, presence of termite or wood-destroying organisms, or compliance with codes, ordinances, statutes or restrictions, or the insurability, efficiency, quality, durability, future life, or future performance of any item inspected. This report is good for the day of the inspection only and is not to be used for Home Warranties or Insurance Underwriting purposes. The digital pictures attached to this report are sample(s only noted within the structure and should not be considered to show all deficiencies and/or damages of or within the structure(s. There are some degrees of defects or damages not represented in or by digital images.

EXAMPLES

When the inspector inspects the roof and or plumbings of a structure he or she may determine that there are no observable signs of water penetration or leaks at the time of the inspection and that the roof and or plumbings appears to be functioning as intended. Even if this opinion is expressed, it is possible that the roof and or plumbing has leak(s but that the storage items, floor coverings, ceilings or walls etc. have been repainted, concealing the evidence as an example. Further, although the roof and or plumbings may be functioning as intended at the time of the inspection, the roof and or plumbings may still need to be replaced, updated and or repaired before close or in the near future etc.

GENERAL LIMITATIONS

The inspector is not required to:

- (A) Inspect:
 - (i) Items other than those *specifically* listed herein;
 - (ii) Elevators;
 - (iii) detached structures, decks, docks, fences, or waterfront structures or equipment;

Page 2 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill. This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

© 2024 Kissee Inspections

Kisseeinspections.com

469.789.1444

- (iv) anything buried, hidden, latent, or concealed; or
- (v) automated or programmable control systems, automatic shut-off, photoelectric sensors, timers, clocks, metering devices, signal lights, lightning arrestor system, remote controls, security or data distribution systems, or solar panels;
- (B) report:
 - (i) past repairs that appear to be effective and workmanlike;
 - (ii) cosmetic or aesthetic conditions; or
 - (iii) wear and tear from ordinary use;
- (C) determine:
 - (i) insurability, warrantability, suitability, adequacy, capacity, reliability, marketability, operating costs, recalls, counterfeit products, life expectancy, age, energy efficiency, vapor barriers, thermostatic operation, code compliance, utility sources, or manufacturer or regulatory requirements except as specifically required by these standards;
 - (ii) the presence or absence of pests, termites, or other wood-destroying insects or organisms;
 - (iii) the presence, absence, or risk of asbestos, lead-based paint, mold, mildew, or any other environmental hazard, environmental pathogen, carcinogen, toxin, mycotoxin, pollutant, fungal presence or activity, or poison; or
 - (iv) types of wood or preservative treatment and fastener compatibility;
- (D) anticipate future events or conditions, including but not limited to:
 - (i) decay, deterioration, or damage that may occur after the inspection;
 - (ii) deficiencies from abuse, misuse or lack of use,
 - (iii) changes in performance of any part, component, or system due to changes in use or occupancy;
 - (iv) the consequences of the inspection or its effects on current or future buyers and sellers;
 - (v) common household accidents, personal potential injury, or death;
 - (vi) the presence of water penetration(s); or
 - (vii) future performance of any item;

(E) operate shut-off, safety, stop, pressure, or pressure-regulating valves or items requiring the use of codes, keys, combinations, or similar devices;

- (F) designate conditions as safe:
- (G) recommend or provide engineering, architectural, appraisal, mitigation, physical surveying, realty, or other specialist services;
- (H) review historical records, installation instructions, repair plans, cost estimates, disclosure documents, or other reports;
- (I) verify sizing, efficiency, or adequacy of the ground surface drainage system;
- (J) operate recirculation or sump pumps;
- (K) remedy conditions preventing inspection of any item;
- (L) apply open flame to operate any appliance;
- (M) turn on decommissioned equipment, systems, or utility services; or
- (N) provide repair cost estimates, recommendations, or re-inspection services.

The Client, by accepting this Property Inspection Report or relying upon it in any way, expressly agrees to the SCOPE OF INSPECTION, GENERAL LIMITATIONS and INSPECTION AGREEMENT included as a part of this inspection and report.

This inspection report does not warrant or guarantee all defects have been found. Such is made for the sole purpose of assisting the purchaser to determine his and/or her own opinion of feasibility of purchasing the inspected property. If you have any questions or are unclear regarding our findings, please call our office prior to the expiration of any time limitations such as option periods. This report contains technical information. If you were not present during this inspection, please call the office to arrange for a consultation with your inspector. If you choose not to consult with the inspector, this inspection company cannot be held liable for your understanding or misunderstanding of the reports content.

This report is not intended to be used for determining insurability or warrantability of the structure and may not conform to the Texas Department of Insurance guidelines for property insurability. This report is not to be used by or for any property and/or home warranty company.

***The Texas Real Estate Commission requires a home to be inspected using today's "Standards of Practice". At the time a home was actually constructed, it may have been governed by different "Standards of Practice".

Additional pages and photos may be attached to this report. (Photos are not a required TREC item & are inserted at the inspector's discretion). Read and review ALL carefully. This report may not be complete without such attachments. If an item is present in the property but is not inspected, the "NI" column will be checked and an explanation is necessary. Comments may be provided by the inspector whether or not an item is deemed in need of repair.

Page 3 of 39

TREC LIMITATIONS: §535.228(n) Specific limitation... The inspector is not required to: (1) Exhaustively observe insulated windows for evidence of broken seals; (2) exhaustively observe glazing for identifying labels; or (3) identify specific locations of damage. This inspection report will note the windows location for the first three windows, with four (4) to six (6) windows to be noted as "Various", and any number over (6) six as "Multiple- Locations". Every client has a different expectation & acceptance for windows appearance and clarity. As the Client/ purchaser you may wish to refer to your seller's disclosure, seller(s) and or the realtors, builder involved with handling - of the buying and selling, building of the structure and determine if there are any concerns in your opinion of the windows, glazing, screens etc. to you. Please keep in mind all bedroom windows are considered an escape/egress in case of fire and are to be fully operational. All observed notable flaws under TREC guidelines will be pointed out in this report, of the accessible windows.

SCOPE OF THE INSPECTION:

Kissee Inspections wishes to remind you, every property requires a certain amount of ongoing maintenance, such as, unclogging and updating drains / drain lines, servicing of furnaces, air conditioners, water heaters, Electricals, etc. This property will be no exception. It is suggested that you budget for maintenance/ repairs as well as change of ownership and or appliances, updating(s, hidden issues, plumbing, etc. Once again the following report is based on visual inspection only of the accessible areas of the property. Please read and study the entire report carefully. Any ancillary inspection outside of TREC minimum requirements is based on the inspection agreement and / or additional information provided at the inspector's option should such not be under fee contract.

"All qualified and Professional licensed contractors who, make further evaluations and or repairs will make the final decision as to what, if any, repairs, replacement or further conditions will or will not be performed and or corrected. Our Report comments are only general information for the buyer on the general condition of the house and its building components. The City Building Officials are the only officials / inspectors who have final jurisdiction over all code related issues. We as TREC inspectors cannot make comments about building components that "pass or fail" inspections." Note: Kissee Inspections services, LLC makes No Guarantee or offer of any warranty of any kind concerning the life expectancy and that all items / issues of any and all systems such as electrical, plumbing, structural, mechanical, HVAC system(s) as examples have been discovered and recorded. It is recommend that the client invest in a warranty, which may or may not cover items such as plumbing, mechanicals, appliances, heating and cooling systems of the structure(s). etc. as examples.

This report shall supersede any written or verbal conversations, comments and or reports that were provided prior to providing this written report.

Re-inspection Policy: We are often asked if it would be possible to re-inspect the problem areas disclosed in this inspection after repairs are made. We have a minimum fee of \$250.00 for this service up to eight (8) items (over eight (8) items, please call the office) Criteria:

- 1) A licensed contractor must perform the repair work if licensing is required for that trade.
- 2) The contractor must provide a receipt indicating the type and quantity of materials used and a description of the work performed.
- 3) The contractor must state whether or not the work is warranted, the length of warranty, and if the warranty is transferable to the new owner.
- 4) These documents must be available at the house when we arrive for the re-inspection. We do not re-inspect any repairs performed by unlicensed contractors or amateurs.

The Inspection Agreement is to remain in force for the referenced buyer(s and property for all current and future inspection services.

Important Notice

Whenever a defect of any kind is noted in a system or aspect of the house, we recommend that a qualified (licensed) technician inspect and service the entire system. Sometimes noted defects are symptoms of other, sometimes more serious, defects. It is also recommended that the buyer walks through the property the day before closing to assure conditions have not changed since inspection. If other built-in or stand-alone appliances are located in this structure such; as but not limited to; Built-in Blenders, Can Openers, Ice Makers, Knife Sharpeners, Wine Coolers, Washers Machines, Dryers, Refrigerators, Freezers or other like appliances; these are not included with this inspection.

Home inspectors make a general inspection of the structure according to TREC guidelines, conducting an essentially visual inspection and recommending specialists in the appropriate area for specific repairs. Some specialists, and other people, may at times disagree with the inspector(s opinions. The inspector(s defer to such professionally licensed specialists opinions. The inspector has put his/ her opinions in writing. The inspector(s feel that for all concerned, you should have each specialist put their opinions in writing, with their license number. If they refuse to do so, it is recommend you establish what weight to give each opinion.

Page 4 of 39

Aprox age of structure/pr	operty. 2007			_
Present at Inspection:	☐ Buyer	☐ Buyer's Agent	☐ Listing Agent	☐ Occupant
Building Status:	☐ Vacant	Owner Occupied	☐ Tenant Occupied	☐ Other
Weather Conditions:	□ Fair	☑ Cloudy	☑ Rain	Temp: <u>>70</u>
Utilities On:	✓ Yes	☐ No Water	☐ No Electricity	☐ No Gas
Special Notes: (Draft)			•	

Page 5 of 39

INACCESSIBLE OR OBSTRUCTED AREAS

☑ Floors Covered	☑ Attic Space is Limited - Viewed from Accessible Areas
☑ Sub Flooring	☑ Plumbing Areas - Only Visible Plumbing Inspected
☑ Behind/Under Furniture and/or Stored Items	☑ Stored Items In Garage
✓ Walls/Ceilings Covered or Freshly Painted	Attic Insulation Covering Attic Floor

Recommendation for Addressing Deficiencies -Whenever a system or component of the house is marked as D=Deficient **and or noted for concerns**, it is the Client's responsibility to find and make arrangements for a qualified professional, or technician to further inspect, evaluate and service the ENTIRE SYSTEM prior to the end of any option or review period. Furthermore, it is the Client's responsibility to instruct any person conducting the review to take into account not only the problem or issue identified by the inspector, but also any adjacent, collateral or contiguous, intersecting and/or hidden/obstructed systems, components or issues that may require repair, replacement or upgrading. By not properly addressing deficiencies, problems or concerns through the repair amendment process, the client is accepting the condition of the property and becomes responsible for any current and or future repairs. SOMETIMES NOTED DEFICIENCIES ARE SYMPTOMS OF OTHER, MORE SERIOUS AND COSTLY, DEFECTS.

Page 6 of 39

I NI NP D

I. STRUCTURAL SYSTEMS


 \square \square \square A. Foundations

Type of Foundation(s): Slab on ground

Comments: (An opinion on performance is mandatory)

The following observations, deficiencies and/or exceptions were noted on this structure at the time of the inspection, such as but not limited to:

- At the inspection time, the inspector did not observe visual evidence that would be consider as signs of, or indications of major movement.
- Signs or indications were, such as but are not limited to, the accessible doors and windows that showed no signs of major movement.
- The accessible attic space showed no signs of major movement.
- As well as the floors showed no signs of typically associated with major movement.
- Corner cracking/ popping was observed, as typical found for the area.
- Some settling of the structure was noted as is typically found in the N. Texas clay (plastic) soil. Further concerns should be directed to a professional engineer and or a foundation contractor.











• One or more of the foundation perimeter beam corners were observed to be cracked/popped. This is a common condition to observe and is typically due to thermal expansion and contraction of the different building materials. This condition does not appear as to adversely affect the foundation performance. However, in some cases, some cosmetic improvements may be necessary.

Page 7 of 39

Report Identification: 20240911-001, 990 Harmony Cir, Nevada, TX							
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient				
I NI NP D							

Low soil back fill height noted, with the bottom portions of the slab showing. Corrections are encouraged.

In the inspector's opinion, the foundation appears to be providing adequate support for the structure at the time of this inspection. The inspector did not observe any visible apparent / obvious evidence that would indicate the presence of adverse performance or major significant deficiencies in the foundation. The interior and exterior stress indicators showed little affects of adverse performance and I perceived the foundation to contain no major significant unlevelness after walking the 1st level floors.

Note: The client is informed at this time that the Inspector is not a Structural &/or Professional Engineer and that this is not an Engineering Report. The North Texas Area has soils that are plastic and movement can be expected. The stated conditions of the structural integrity and characteristics of the foundation are based on the experience of the Inspector and the comments made concerning the structural soundness or structural deficiency of the foundation is the opinion of the Inspector and is based upon the visual observation and evidence observed at this time of the inspection. No special test, leveling, straight-line comparisons, lasers, etc., are made during the inspection. If any cause for concern is noted on the report or the client observes any item of concern that is not listed on the report, the client should consider an evaluation by a Structural Engineer.

\square \square \square B. Grading and Drainage

Comments: The inspector's opinion is the grading and drainage, appeared to be performing with the following observations, deficiencies and/or exceptions being noted on this structure, such as but not limited to:

- The soil line is low. Under current building standards there should be at least 4-inches of foundation visible below masonry veneer and 6-inches of foundation visible below wood type veneer.
- Gutter / down spout(s noted as dented / damaged.
- Gutters should have complete and secured extensions -to divert the water away from the foundation. Recommend installing gutter extensions.

Notice: It is impossible to determine if all lots/yards are adequately draining without the use of special equipment and or being present during a rainstorm, which is not within the scope of this inspection. Low areas or conditions that appear to be a drainage problem will be reported.

Notice: Proper Drainage And Soil Moisture Contents Should Be Maintained Around The Foundation To Help Minimize Future Foundation Problems. We Make No Statement Concerning Site Stability. It is generally recommended that you water outside of current root area to assist roots to grow outside of foundation area.

☑ □ □ ☑ C. Roof Covering Materials

Type(s) of Roof Covering: Asphalt Shingles

Viewed From: Roof Level

Comments: The inspector's opinion is the roof covering, appeared to be performing with the following observations, deficiencies and/or exceptions being noted on this structure, such as but not limited to: Due to steep roof pitches; all areas of the roof were not accessible under foot and were viewed as best as possible from the areas accessible under foot-roof top vantage points.

Note: The inspection of the roofing may show that such is functioning as intended or in need of repair. The inspection does not determine the insurability of the roof. You are encouraged to have your intended insurance company to physically inspect the roof prior to closing to fully evaluate the insurability of the roof. The performance of this roof is subjective and is sometimes difficult for two individuals to agree on the life of a roof, etc., you may wish to consult a qualified roofing specialist to determine further conditions and provide a maintenance schedule for the roof.


Page 8 of 39

I NI NP D

Notice: Gutters terminating on shingles have been known to cause premature deterioration and or damage to shingles and could void manufacturers warranty. Recommend consulting manufacturers installation procedures and recommendations for this type of application.

The structure has a hip and ridge type roof. Portions of the roof & roof fasteners were inspected from the attic space. Roof Covering appeared to be installed by nailing.











Page 9 of 39

I NI NP D



- There was no kickout flashing details observed at the lower bottom edge of the roof line interface and the sidewall that continues past the edge of the roof. The lack of this kickout flashing will allow water to penetrate at these points.
- Worn / scuffed covering noted. Refer to a roofing contractor for recommendation/ repairs/ replacement options.
- Notice: Refer to your seller for further information. Contact your insurance company & see if they will pull a CLUE report before closing to better inform concerning your future purchase. C.L.U.E. (Comprehensive Loss Underwriting Exchange) is a claims history database generated by LexisNexis® that enables insurance companies to access consumer claims information when they are underwriting or rating an insurance policy.
- Notice: Some pest control companies have been known to cause alarm to home owner's with gapping in soffit to roof line junctions. Such are not to have wood and or wood like material in contact with the roof covering as well as a home's attic are to breath. Some individuals have been known to foam seal closed gaps, and others to apply metal flashing in such areas. Refer to your engineer of records and /or your builder for further details, etc.

Notice: Weather events can and do occur after the time and or date of the inspection which may produce significant damages. The client is warned to have the structure further inspected immediately before closing, to ensure all is to the client's and insurance underwriting's expectations and approvals (as a minimum).

oxdot D. Roof Structures and Attics

Viewed From: floored area of the attic.

Approximate Average Depth of Insulation:0 to 10+

Comments: Proceeding beyond supplied flooring could be hazardous or damage the integrity of the insulation. Approximately <20% of the attic was viewable. The inspector's opinion is based on the viewable and readily accessible areas.

Insulation Type(s): Blown

The inspector's opinion at the time of the inspection was the roof structure and attic, were noted with the following observations, deficiencies and/or exceptions being noted on this structure, such as but not limited to:

Radiant barrier present/visible: ☐ Yes ☐ No-none within view @ time of inspection

Page 10 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill . This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

© 2024 Kissee Inspections

Kisseeinspections.com

Access Type:	☑ P/D Stairs	☐ walk in door(s	☐ Scuttle Hole/ Pop-up opening

P/D Stairs with insulation ☐ Y ☑ N ☐ N/A

Roof Structure: ☑ Rafter Assembly ☐ Truss Assembly

Report Identification: 20240911-001, 990 Harmony Cir, Nevada, TX

Ventilation Roof / Attic: ☐ None ☐ Static Ports ☐ Soffit Vents ☐ Turbines ☐ Powered Fan ☐ Gable ☐ Ridge

Insulation & Ventilation:







- Compressed insulation noted and should be rearranged, improved as deemed / desired necessary.
- What appeared as past attic Rodent tunneled/ pathway areas and packed down insulation noted. Insulation improvements are considered as in need. Consult with seller(s) concerning any past pest control efforts if performed and success if such was effective as well as any warranty if in place and conditions, etc.
- Attic is in use with storage items and is recommended to be cleared out and further inspected with any corrections, repairs performed before closing should such exists.

Notice: In the N. Texas region its not unusual to find temps in attic to be higher in summer time heating than at the time of the inspection visit. Should such high temps exists, consideration of additional soffit and roof top venting with baffles may be desired, as an example. Refer to an attic vent company professional such as "Lomanco Vents Co." or others for further advice, designs and installation, guaranties /warranties etc. Too: Attic access such as pop-up opening(s with no ladder provided or other means for the inspector to approach are considered as not accessible. Further review(s / inspection(s should be obtained before option period expires.

☑ □ □ ☑ E. Walls (Interior and Exterior)

Comments: The inspector's opinion is-one or more of the walls, were noted with the following observations, deficiencies and/or exceptions being noted on this structure, such as but not limited to:

Description of one or more of the exterior cladding(s:

☐ Wood veneer ☐ Brick Veneer ☐ Stone Masonry Veneer ☐ Vinyl Siding ☐ Man Made Board

Page 11 of 39

I NI NP D







- Exterior & interior wall frames, sills, and penetrations, wall expansion joints; glazing/caulk/grouting needs- up keep/maintenance/repairs. Recommend all areas to be serviced at the purchaser's &/or repair professional's discretion.
- Caulking improvements are recommended for the area between the exterior veneer and the window / door frames, etc. It is recommended to use an <u>elastomer caulking</u>.
- Evidence of patching was detected of the wall(s as viewed at the front entry door area of the structure as an example, refer to seller for further details.

Notice: Property occupied with furnishings, therefore some areas of the floors were not / could not be inspected due to personal items covering floored areas as well as the furniture blocking access to walls.

\square \square \square \square F. Ceilings and Floors

Comments: The inspector's opinion is ceiling and floors, appeared to be performing with the following observations, deficiencies and/or exceptions being noted on this structure, such as but not limited to:

Ceiling



- Note(s):RULE §535.228 (e) (1) (iii) Interior walls, ceilings, floors, and doors. (e)(1)The inspector shall: (B) report as Deficient: (iii) lack of fire separation between the garage and the living space and between the garage and its attic. 06 I.R.C. [309.2][309.1] CABO 309.2 (https://texreg.sos.state.tx.us)
- Fire stopping in the garage ceiling was not complete (Attic access). When a garage is attached to the structure, special considerations must be taken into account. The absence of this fire barrier can allow a fire to draft into the attic. The absence of such barrier is considered as a recognized hazard. This is a common callout for this region with builders / contractors installing attic accesses in the attached garage ceiling(s) with no fire separation in the garage attic to the main structure's attic. Some municipalities have not enforced this standard by with inspectors are to call out; as previous noted above.

Page 12 of 39

I NI NP D

- Cracks noted with in the ceilings in various areas. *Note:* These areas appear as expansions cracks from attic heating and expanding due to heat build up in the attic space.
- Past repair, patching, etc of the ceiling noted. Refer to the seller and seller's disclosure for further information. (as note at the Multiple locations area as example.
- Nail heads were observed to be pushing through the interior finish in one or more locations.

Notice: Property occupied with furnishings, therefore some areas of the floors were not / could not be inspected due to personal items covering floored areas as well as the furniture blocking access to walls.

☑ □ □ ☑ G. Doors (Interior and Exterior)

Comments: The inspector's opinion is the doors, appeared to be performing with the following observations, deficiencies and/or exceptions being noted on this structure, such as but not limited to:



- The garage service door closer hinge spring was noted as not fully closing the door on a one foot swing.
- The door to the laundry room was noted to have a large gap along the striker plate side to the point it can pass the door stop as well as rubbing at the top corner.
- One or more of the doors for the structure interior were noted to be lacking detent ball and springs.

☑ □ □ ☑ H. Windows

Comments: The inspector's opinion is-the accessible windows, were noted with the following observations, deficiencies and/or exceptions being noted on this structure, such as but not limited to:

Multiple areas such as but not limited to:

Notice: Dirty/ dusty windows. Units were observed as best as possible under the conditions found.

Page 13 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill. This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

I NI NP D

Notice: Most /all of The windows are older. They are in a state of mild disrepair. Trimming and/or adjustment, hardware improvements, and weatherproofing improvements could be undertaken as / if necessary. In practice, improvements are performed on an as needed basis. Installing replacement windows may be the best long term approach. In the interim, it is important that the window exteriors be well maintained to avoid rot or water infiltration.



- The windows appeared to have loss of thermal seals, as noted at/ in multiple locations around the entire structure such as noted in the living areas, dining room and bedroom areas. See Pics above as examples.
- Exterior window(s sealant show separation/ age / in need of servicing/replacement/. Recommend all areas to be serviced at the purchaser's &/or repair professional's discretion.

Notice: Property occupied, therefore some of the windows or parts thereof may not have been accessible and inspected due to personal items, such as furniture, etc. blocking access to them.

Representative samples of the windows were inspected to ascertain if the thermal seals had failed, checked for cracked glazing (major and minor), and evaluated for water/ moisture impaction. Often, a failed seal may not be identified during an inspection because of weather conditions, humidity, and / or lack of cleanliness. Anomalies such as the accumulation of water when there are extreme temperature variances between interior and outside air can occur at different times throughout the year. As thermal pane windows lose their vacuum, moisture may appear between the glass and then disappear, depending on the inside/ outside

Page 14 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill. This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
window that may were inspected on a broken seal, dan the scope of this inspected and che detected. When lo	have a damage seal. Therefore in a "best efforts" basis. We can a mage, or other inconsistencies, it inspection. Therefore windows tacked for operation. There is a particular of the second of the se	, we can make no representa assume no responsibility for it was as a result of observation as are listed as observed at the cossibility that lost seals, dan oted it is recommended that	the inspector will make no attempt to identify every tions as to the condition of every window. Windows tems not observed on our visit. If we note evidence of as at the time of inspection. Product recalls are beyond the time of the inspection. Accessible windows will be tage, or other inconsistencies exist that have not been all windows be rechecked by a window specialist for or warranty periods.
warranty transfer		ommended that you walk the	repair(s, adjustment(s to your window(s, and any such e structure before close with windows cleaned and all
	I. Stairways (Interior and Comments: N/A	d Exterior)	
	concealed / inaccessible	ey review is limited to the vise portions of the chimney and	ible / accessible components only. Examination of firebox is beyond the scope of this inspection. This if a lining is present. The following is the inspector's

Fireplace & Chimney - the following observations, deficiencies and/or exceptions being noted on this structure, such as but not limited to:

opinion.

Number of fireplaces: 1 Fireplace location: Living Area Type of Fireplace: Metal box and flue Coping, Cap & Crown was inspected from Roof top **Spark Arrestor / Rain Cap – Present:** ✓ Yes ☐ No ☐ Not available for viewing Saddle / Cricket / Hip or Ridge – Present: ☑ Yes □ No Chimney Condition-Chimney/cap/ crown intact and ☑ Yes ☐ No ☐ Not available for viewing appears serviceable where visible: Chimney Flue- Chimney Flue appears serviceable where ☑ Yes □ No visible: Chase / Flue Siding shows visible; rot / water ☐ Yes ☐ No ☑ Not available for viewing 100% impacted/damaged: **Chimney Flue missing fire-clearances:** ☐ Yes ☐ No ☑ Not available for viewing **Creosote / Ash - in Chimney Flue:** ☐ Yes ☐ No ☑ Not available for viewing Cracks/damaged in Firebox and/or Chimney: ☐ Yes ☐ No ☑ No-none within view @ time of inspection **Screen present or installed:** ☑ Yes □ No Log rack Present: ☑ Yes □ No Damper: ✓ Operational ☐ Not operational/damaged ☐ None present ☐ fixed-open venting/Direct Vent

The chimney / flue should be initially, as well as annually cleaned, further inspected and repaired as required by a professional fireplace company before use, and option period expires

Page 15 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill . This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

[=]	I=Inspected				NI=Not Inspected	NP=Not Present	D=Deficient
I	NI	NP	D				
□ Co.	☑ mmei	☑ nts:	_		Porches, Balconies, Dec decking, porch, etc.	cks, and Carports	
				L.		lowing observations, deficienc	is-the following noted item(s), appeared to be cies and/or exceptions being noted on this structure,

- WDI is a separate report
- Cracked drive way/garage floor/pool deck. Recommend monitoring for movement,etc.; any further concerns are deferred to a foundation contractor or a professional engineer.
- Gate / fencing requires repairs at one or more location. Structure is noted to have a pool. Refer to "Pool" section below as well as cps / nspf for pool fencing enclosures.

Notice: Cockroach, Non-Wood Destroying ants, snakes, mice, rats, racoon, squires and other creatures, pest and insects are not part of a TREC report / inspection; as well as such possibly may not be classified under the TDA (Texas Department of Agriculture) as wood destroying insects. Should such concerns exist refer to your seller's disclosure as well as professional pest control company(ies for further details, concerns and any possibly remedies, as a minimum. Any bold prevalent signage of such are included as a courtesy.

II. ELECTRICAL SYSTEMS

 \square \square \square A. Service Entrance and Panels

Type of Wiring:Copper

Comments: At time of inspection the opinion of the electrical in view is noted as;

Type of Main Service wiring was: 250/125v Copper

The Main Service system appeared to be performing with the following observations, deficiencies and/or exceptions that was noted on this structure, such as but not limited to:

- The main service conductors entered the structure underground and were tied to a Cl 200 amp meter.
- The meter was located on the exterior garage wall of the structure.
- A grounding rod was noted to be in view extending above the ground/ grass surface with the grounding clamp revealed.
- The main electrical panel was located in the interior garage.
- The structure has a 200 main breaker.
- The electrical panel box appears to be a 200 amp minimum type box.
- Trip ties appeared to be installed on 240 volt circuits.
- All Branch wiring appears to be Copper.
- Neutrals and grounds are wired on separate bus bars.
- No GFCI protection installed for the dryer outlet.
- A sub panel box was located Left of the main panel.
- The sub panel was noted as supplied with four wires with neutral and grounds on separated bus bars.
- Notice: 2020 NEC 230.67: Currently all new built homes in Texas under the NEC are required to have whole house surge protection (Surge Protection device (SPD)). The inspector is Not a Code enforcer and does not work on behalf of the municipality or Authority having Jurisdiction (AHJ). The home as found did not have such in place.

Page 16 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill . This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

I=I	Inspe	ected		NI=Not Inspected	NP=Not Present	D=Deficient
I	NI	NP	D			
	•	Neu	trals a	nd or ground double tapped. (n	nore than one wire under one	lug)□ Yes □ No ☑ 100% not in view.
	Not			nilds now require AFCI. A hor		
No	otice:	AFC	I typ	e breaker, shared bus bars, as	well as the installation of ufe	acceptance of the builder(s as to & for location(s of er and or ground rods protruding as an acceptable or building official for further details or concerns.
				A professional licensed ele	ctrician should inspect an	d repair as needed.
V			V	B. Branch Circuits, Conn Type of Wiring: Copper	ected Devices, and Fixtures	
					lowing observations, deficienc	cuits, connected devices and fixtures appeared to be cies and/or exceptions being noted on this structure,
	<u>Ger</u>	Elec	trical		l Yes ☑ No-none within view e upgraded with battery rep	$v \ ext{ } ext{ } $
		is re exan		ended to replace the batteries i	n all of the smoke detectors as	t least once a year for reasons of safety, as an
	•	dwe	lings 1	with attached garage. (ref: NF)	PA 720) Lack of alarm is cons	ent requirements state such devices to be installed for sidered a fire safety hazard. Carbon Monoxide to your manufacture for further details.
	•	Min pane		amp dedicated circuits for the	e counter-toped kitchen, lab	eled at panel and in view? (per label @ main
			ΖDΝ	☑ Unknown panel not marl	ked properly/ specifically/ leg	gible.
	•	20 a	mp ci	rcuit for the bath(s (per label	@ main panel)	
			'□Ν	✓ Unknown panel not market	ed properly/ specifically/ legil	ble.
	•	Out	side re	eceptacles in wet areas - bubb	ole cover(s -present and wor	king in all required areas.
			'☑N	•	all exterior wet area receptac	<u>les to have bubble covers</u> .
	•		_	t the water heater in view:	\square Y \square N	
	•			ealing in need around exterior l		
	•	Ligh	t guar	ds in need around attic light bu	llbs. \square Y \square N \square no light	available

Page 17 of 39

NI=Not Inspected

I NI NP D

I=Inspected



Switches, Fans & Lights

• Lighting noted as not working at the time of the inspection as observed at/in the, various locations as examples.

NP=Not Present

D=Deficient

Electrical Branch Outlets

• **Ground Fault outlets protections** (GFCIs) in the structures are not properly working and/ or installed (as currently required) in all areas. Example: All-Kitchen counter tops, baths, garage receptacles, All-areas with in a 6" of a wet zone (i. e. kitchen sink as an example), exterior outlets etc.





Example

- Noted kitchen back splash has/have receptacles/ switch boxes recessed with no extension spark arrestors (goof) rings in place at one or more location.
- Notice: Homes and or structures that are occupied by personnel and or items will not and were not inspected of *all* GFCI tripping performance due to liability of locating and resetting power to electrical appliances, and or devices which may lead to loss of property, content and or damage to items such as food and electronics as examples. *The Local Authority Having Jurisdiction (AHJ) has final approval and acceptance concerning adoptions of new / current electrical codes such as afci / gfci locations and requirements. As an example; such as at all garage and kitchen areas such as but not limited to garbage disposal, overhead door opener, etc. The Inspector is licensed as a TREC inspector and not code enforcement. All other concerns are directed to your local AHJ.*

A professional licensed electrician should inspect and repair as needed.

The inspector will describe the type of branch circuit wiring and inspect the visible and accessible parts of the system. GFCI should be at all kitchen countertop and bar sink receptacles, in bathrooms, at all garage and exterior receptacles. Most-all other 15-20amp outlets should have AFCI (Arc-Fault) protection. Smoke detectors should be in all sleeping rooms and adjacent hallways and at tops of stairs, and on each living level of multi-story home. Telephone/TV/ computer wiring/devices are not inspected. Lights, fans, and

Page 18 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill . This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

I=Inspected	ntion: <u>20240911-001, 990 H</u> NI=Not Inspected	NP=Not Pres		nt
I NI NP D		111 1100 1100		
other difficult a viewed as requi TREC LIMITA effectiveness o	ccess areas are not inspected ring specialized equipment & TIONS: The inspector is not f smoke alarms; verify the	unless specially noted. Elector further electrical trainit required to inspect low vinterconnectivity of smo	ectrical Bonding is not conng. oltage wiring; disassemble alarms; activate smokens.	tlets in soffits, behind shrubbery or firmed as 100% complete as such is e mechanical appliances; verify the alarms that are being or in the alarms are suitable for the hearing-
	III. HEATING	, VENTILATION A	ND AIR CONDITIO	NING SYSTEMS
	Type of System: C Energy source: E Comments: The ind deficiencies and/o Location: Attic a	Central -HeatPump Electric-heat pump spector's opinion is the hea or exceptions being noted o	n this structure, such as b	d with the following observations, ut not limited to:
The design, sizi engineer.	ng, capacity and efficiency of	f the system can only be do	termined by a licensed HV	VAC contractor and /or mechanical
A full evaluatio	n of the integrity of a heat exonis is a specific T.R.E.C. guid		ng of the furnace and is be	eyond the scope of this visual
	switch for blower supply:	☑ yes	□ no	☐ No-none within view
	ptacle within 20':	☑ yes	□ no	☐ No-none within view
Furnace(s)):	☐ Partially accessible	☐ Fully accessible	✓ Not accessible
• The therr	nostat in the rear living r	room area has electric l	•	ing system.
	Type of System: C Comments: The in deficiencies and/o Interior Locatio	Central split system	n this structure, such as b	oted with the following observations, ut not limited to:
engineer. Note: sealed over, etc	Covers are not removed from	n the evaporator coil box to dismantling of the vent pip	inspect the condition of the is required. Gauges are n	VAC contractor and /or mechanical he evaporator coil when taped not placed on air conditioner units to sional.

Page 19 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill . This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

I NI NP D

Notice: The client is encouraged to have a professional licensed HVAC Company personnel perform further inspection to satisfy any and all Home Warranty needs, as past client(s have expressed denial for coverage due to item(s such as may or may not have been indicated on a third party inspection report. Although this and any inspection report is performed on behalf of the client and is not for a Home Warranty Company to base their coverage, many Home Warranty have practiced such in their business concerning client coverage. (A Home Warranty company has not hired the inspector and or the inspection company and such is stated in the beginning pages of this report as NOT for their coverage bases.) Refer to your lawyer for further details.

- Comments: Refer to the seller(s / tenant(s concerning any past repairs, servicing or replacement(s that may have been performed.
- The systems appeared as older system(s. Such may require a slightly higher level of maintenance, and may be more prone to major component breakdown. Predicting the frequency or time frame for repairs on any mechanical device is virtually impossible.
- Contact a 3rd party (Not-affiliated to Inspector, Builder, Realtor, Etc.)-licensed professional (Non-technician) HVAC contractor, mechanical engineer for "Report of HVAC Testing and Balancing", sizing, adjusting, etc. of the HVAC unit(s).

What appears as the possible locations and information as deciphered for the exterior units are noted as the following examples:





Today's Temperature Differential (Delta-T): 18 Degrees

Approximate System Age: 2018 Approximate System Size: 2 ton

Brand Name: Rheem Coolant Type:410-A

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D





Today's Temperature Differential (Delta-T): 17 Degrees

Approximate System Age: 2007 Approximate System Size: 3 ton

Brand Name: Carrier Coolant Type:R-22

Notice: The Federal EPA has currently scheduled all use of R-22 gas to cease by the year 2020. Replacement gas for any HVAC equipment may not be available commercially. Refer to a professional HVAC company for further details.



- One or more of the AC Condensation pans noted as being rusted/ with rust. Repair /replacement should be considered. Refer to the seller(s concerning prior repairs if performed as well as any warranty which may be present and if transferable.
- Water noted in the pan.

Notice: While the units do appear to be sufficiently cooling at the time of the inspection, it would be wise to such serviced and further evaluated before the summer months. Temperatures were in the 70s during the inspection.

Page 21 of 39

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
cooling system. Ou difference (Delta-T Department, Colle- humidity, high or I functioning basical inspector will not be changes in use or co	ar company policy's normal accorning to measured between the return ge of Architecture Texas A&N ow outdoor temperatures or resulty as designed and occasionally be able to anticipate future even	eptable range is considered as air vent and supply air vent of I University uses 15-20 degree tricted airflow may indicate al may indicate normal operations, conditions or changes in perpector and / or inspection compared to the conditions of the conditions of the conditions or changes in perpector and / or inspection compared to the conditions of the	ractice for testing the proper operation of the approximately between 15 to 22 degrees °F total f the system being evaluated. [Construction Science es]. Conditions such as but not limited to; excessive proormal operation even though the equipment is on in spite of an equipment malfunction. The erformance of any component or system due to apany makes no guarantee or warranty, express or
Rec	ommend professional seasona	l servicing and repairs of the	e air handling system.
		from floored access only. The	inspector's opinion is the duct system, chases and exceptions being noted on this structure, such as but
the efficiency, adequa	acy or capacity of the duct system of	or to test for fungus, mold, milder	ned air to the various parts of the structure or to determine w or bacteria. Environmental issues are not verified. The other inaccessible areas cannot be determined.
	ed in: Attic (attached to the air and addition: had some dirt	handler) Approx Size of Fi	ilters: Various Air Chase Dirty: N/A
• Air Ducts	: -ok (what was in view)		
bedrooms			l to flow from room to hallway at one or more f records and /or your builder for further details,
refrigerant, type o motorized dampers units, supplemental cooling equipment gas-fired heating a accuracy of thermo	f refrigerant, or refrigerant leads, electronic air filters, multi-stall heating appliances, de-icing provided when the outdoor temperature appliances; or heat pumps whereastats; or the integrity of the heat	aks; winterized evaporative of age controllers, sequencers, he rovisions, or reversing values is less than 60 degrees Fahren nemperatures may damage texchanger; or determine sizi	ostats or controls; inspect for pressure of the system coolers; or humidifiers, dehumidifiers, air purifiers eat reclaimers, wood burning stove, boilers, oil-fired; operate setback features on thermostats, or controls heit; radiant heaters, steam heat systems, or unvente equipment; verify compatibility of components; thing, efficiency, or adequacy of the system; uniformity materials contained in insulations.
		IV. PLUMBING SY	STEMS
	A. Plumbing Supply, Distr	ribution Systems and Fixture	es
The wate Moveme Main w a	n of water meter: er meter was checked for any ment noted indicating possible lead ater supply valve: (Refer to a later pressure reading:	kage: Y M N/-none seller for further details)	☐ Rear yard/ alley found $60 \ \Box 60 \ge \le 80 \ \Box \ above \ 80 \ psi$
This is a personal, p	rivate and confidential report w	Page 22 of 39 ith all rights reserved by Kisso	ee Inspections and the client, Kristina Malone & ns TREC # 23852. Written permission must be

obtained before being issued to anyone other than the buyer on page one of this report. © 2024 Kissee Inspections

	pecte	d	NI=Not Inspected	NP=Not Present	t D=Deficient	
I N	I NI	PD				
	p T C tl	revent de Sype of si Comments ne follow	amage to the lines and or fixta upply piping material: Copp :The inspector's opinion is the ing observations, deficiencies	ares. er (that which was in vice plumbing supply, distress and/or exceptions being	idence without the installation of a pressure regulator ew) ibution systems and fixtures appeared to be performing g noted on this structure, such as but not limited to: for approximately 15 minutes at a rate of approximate	g wit
			minute for a total of 45 gallo			y 1
•			ings appear as, and are consist deemed necessary, and /oi		of; in need of updating for performance, corrective	
•	V	Vater So	urce: 🗹 Pub	lic □ Private Se	wer Type Appears As: □Public ☑ Private	
			Type of Supply Pipes:	Plastic and Copper		
			Number of bathrooms	: 3		
			Bathroom Group: MB	R		
			Pieces: (5)			
			Commode:			
•	M	BR Com	modeis loose			
			Bathroom Group: Jac	k and Jill bathroom		
			Pieces: (4) Bathroom Group: G Pieces: (3)	uest bathroom		
			Tub / Shower:	l enamel noted.		

Backflow Protectors Present: Y N-Not 100%

Functional Flow: $\mathbf{\nabla} \mathbf{Y} \mathbf{D} \mathbf{N}$

Hot Water Temperature:117°

Recommended Hot Water setting should between 115 – 120°

- Freeze protection required.
- Notice: The washer and dryer are connected, unable to check the laundry utility lines.

Notice: The condition of underground, in walls and restricted access (such as occupied homes with under cabinetry items in place) -water, gas, waste, and vent lines, behind appliances such as refrigerators, ice makers, washers, etc. cannot be determined within the scope of this inspection. Static and hydrostatic, gas pressure test are not part of this inspection. Leaks may be present that cannot be detected within the scope of this inspection. Shower pans are not accessible and inspection results are not conclusive. Hose bibbs for washer/ washing equipment can leak at any

Page 23 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill . This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

© 2024 Kissee Inspections

Kisseeinspections.com

469.789.1444

I N	spect	ted	NI=Not Inspected	NP=Not Present	D=Deficient
1 1	NI N	IP D			
				ttempts to inspect bibbs are mad e expected of any and all plumbi	e and noted for the time of the inspection only. Changes in ng.
☑ [Type of drain Comments: The Checked. The Observations, Clean Outs I	inspector's opinion is that the deficiencies and/or exception coation: Various-exterior rain Flow: Y N	(that which was in view) ess / inspection panels behind he plumbing drain waste and v ons being noted on this structu and interior of home	one or more tub(s). Overflow gaskets and drains not yent appeared as; were noted with the following are, such as but not limited to:
				er faucets that were ran for apns running from the faucets.	proximately 15 minutes at a rate of approximately 1
			"See Fixtures above in	IV Plumbing "A""	
hydro or pro	ostat ofess	ic inspected ional realtor	by a licensed plumber to for seller's approval in wri	confirm the underground co ting of such inspection, etc.	to have the structure's main lines video and/or indition of such drain lines. Refer to your seller and/or seller a
	iergy ocatio		Electric Garage	0. D	
Lo # d Ap	prox	ats: MIL cimate Capac cimate Age: Name:	□ 2 □ 3 city: 50 Gallons 2007 American	On Demand unit (s): ☐ Y	ET IN

Page 24 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill . This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

I=I	nspe	ected			NI=Not Inspected	NP=Not Present	D=Deficient
I	NI	NP	D				
uni	ts the	at are	e over 1	0 yea	urs old are considered bey		y year of sentiment as an example, as well as such ormal service life and all repairs servicing / ed licensed plumber.
V		□ with	☑ the fol			r's opinion is the hydro-mass	age therapy equipment,appeared to be performing oted on this structure, such as but not limited to:
	No				cessible inspection access ment change out/ servic		alled and available for inspecting the tub's under
	•	Acc	ess pan	el no	ted as sealed shut		
	•		bondin 's moto		ap/ connection could be	confirmed as in place with	the manufacture's supplied lug as noted at the
	•	Not insp	ice: Per ection	r TRI is to l	be indicated "Deficient" i	n the TREC inspection form.	strap lug and no bounding strap present the The unit may have been installed according to the ch instruction and details available.
				Ε.	Gas Distribution System	ms and Gas Appliances	
Cor	nmer	ıts:N	/ A				
						V. APPLIANO	CES
				A.	Dishwashers Comments: The inspecto inspection. Manufacturer: Whirlpoo		oted item(s), appeared to be performing at the time of
V				В.	Food Waste Disposers Comments: The inspect of inspection.	or's opinion is-the following r	noted item(s), appeared to be performing at the time
☑				C.	Range Hood and Exha Comm performing at the time of Type: Circulating	ents:The inspector's opinion i	s-the following noted item(s), appeared to be
\square				D.	Ranges, Cooktops, and Comments: The inspecto inspection. Manufactures: Kitcher Type: Electric	r's opinion is-the following no naid	oted item(s), appeared to be performing at the time of

Page 25 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill . This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

Rep	ort Io	lentii	fication	n: <u>202</u>	40911-001, 990 Harmo	ony Cir, Nevada, TX		_
I=Inspected					NI=Not Inspected	NP=Not Present	D=Deficient	
I	NI	NP	D					
☑ Not	□ e: Mi	□ icrow	□ aves are		of inspection. Manufactures:		noted item(s), appeared to be performing at the tim hecked for radiation leaks or temperature control.	2
V				F.	Comments:The inspecto		oted item(s), were noted with the following oted on this structure, such as but not limited to:	
	•	No exterior vent terminations found to be installed for the installed units. <i>All exhaust fans should discharge to the building exterior. This is an "as-built" condition but Per TREC standards of practice we are required to report this condition as a deficiency.</i>						
	Not				are now required to vent I to be: "Not terminating		REC Standards of Practice we have to note this item	
V			V	G.		r's opinion is-the following n	oted item(s),appeared to be performing with the s being noted on this structure, such as but not	
	Model: Genie Sensor Applied: ☑					r Applied: ☑ Y □ N		
	•	show is co	Safety reversing mechanism (@ approximately 5 Lbs.)- did not operate when the door[s] were obstructed as noted both of the car door units. When the inspector tests the safety reversing mechanism of the garage overhead door, the moth hould reverse itself. (5 lbs. Of pressure over a 2 second period should be sufficient to reverse most doors) failure to reverse considered a recognized hazard by the Texas Real Estate Commission (T.R.E.C). These motors can usually be easied justed to operate properly.					
	•					er TREC's guide lines) when t ted the doors can be damaged	he door has an automatic door opening unit. If the	
			-		ould be 4-6" from the floor.	Ç		
V			Ø	Н.			oted item(s),the following observations, deficiencies as but not limited to:	,
		H			100000			



Page 26 of 39

I NI NP D

- Cleaning of the dryer vent piping/ system is in need. / Unit found with lint build up.
- The dryer duct termination is not properly sealed on the attic side of the roof structure penetration and is allowing dryer lint to fall back into the attic area.

Recommend routine cleaning of the dryer venting to insure that no lint build —up is present in the vent line as well as; air exhaust flow is unrestricted and termination to an exterior location is proper/ complete.

Notice: On some build design and use, the termination of the dryer may not be in view and found, such as buildings with steep roof and / or inaccessible attic areas. Inspectors do not perform specialized investigation such as blower -exhaust testing. The client is encouraged to have all dryer piping cleaned and termination confirmed and safe, before use.

 \square \square \square \square I. Other

Comments: N/A

VI. OPTIONAL SYSTEMS

☑ □ □ ☑ A. Landscape Irrigation (Sprinkler) Systems

Comments:

Mfg: Rain-Bird Number of Stations: 9

Location of controls: Interior garage wall Location of back-flow device: Front yard Location of rain/freeze sensor: garage roof/eves

Lawn and Garden Sprinkler Systems: -the following observations, deficiencies and/or exceptions being noted on this structure, such as but not limited to:











Page 27 of 39

Report Identification: 20240911-001, 990 Harmony Cir, Nevada, TX

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

- One or more broken head or line as well as some Sprayer head(s) noted as leaning / not vertical and not surfacing past turf and or not retracting after operating.
- Water from the sprayers were noted as directed unto hard scape and structure, etc.
- No working rain sensor was found to be present. Under current TCEQ guide lines for irrigation/irrigator; such are to have a rain sensor installed.
- A Backflow preventer was not found to be present and readily accessible.
- No Labeling provided as required under the TCEQ as pertaining to the License Name and Number for the irrigation installer. Refer to your builder / seller for further information and or the TCEQ for further details.
- Notice: No designed approved TCEQ plans were found to be available for the purchaser, inspector, etc. at the Lawn and Garden Sprinkler Systems controller location. Refer to your builder or the Texas TCEQ for further details;

(30 TAC §344.61 (a) An irrigator shall prepare an irrigation plan for each site where a new irrigation system will be installed. A paper or electronic copy of the irrigation plan must be on the job site at all times during the installation of the irrigation system. A drawing showing the actual installation of the system is due to each irrigation system owner after all new irrigation system installations....

Professional investigation/repairs are encouraged to conform to current requirements.

☑ □ □ ☑ B. Swimming Pools, Spas, Hot Tubs, and Equipment

Check Box and narrative follows as observed:

Comments: All functions were performed at the clients controls located at the outdoor equipment controller. No programming or throwing of manual valves is performed due to possible liability of breakage. Recommend you consult with the seller and or a professional pool installer / repair company; for all programming and other concerns.

Notice: CPSC has made a multiple recall in 2011 of drain covers. <u>Drain covers are not inspected, concerning recalled product(s.</u> Consult an expert" on drain covers. *No one will know what they have unless they replace such with the latest model(s. Further information can be found at the following link as example or further google searches and other pool professionals.*

https://www.cpsc.gov/Recalls/2011/frequently-asked-questions

Notice: The Following is a list of items in view at the time of the inspection. Please keep in mind that wind, clouds, rain and other environmental conditions can and Do present conditions that can and Do prevent limited viewing. The inspector will and does the best possible to work on the clients behalf to gather as much information as possible at the time of the inspection visit. Further review of seller's disclosure as well as by current and future pool company personal may reveal additional information and or concerns.

Notice: Drainage/ water run off away from the pool, is recommended to be monitored to ensure such is adequate for the build design. Such is beyond this inspection and any correction is deferred to a pool build/ design contractor.

Notice: Due to past winter weather events of freezing temps and electrical power outages the system(s may reveal future issues that may not have been found/ discovered at the time of the inspection visit. Monitoring is required as a minimum.

The inspector's opinion of the Pool and Equipment is such as: the following observations, deficiencies and/or exceptions being noted on this structure, such as but not limited to:


Page 28 of 39

NI=Not Inspected

NI NP D

I=Inspected

Descriptions/ Observations:



Page 29 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill . This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

D=Deficient

NP=Not Present

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

CONSTRUCTION TYPE: In Ground

DECK(S)/POOL COPING: Concrete

 Some cracking of the concrete slab on ground for the pool deck surface was observed at the time of this inspection. You are strongly encouraged to have the cause and remedy further evaluated by a qualified technician, and or pool contractor prior to close.

POOL SURFACES: Liner type

- Satisfactory where visible
- Cleaning is due, dirt sand noted at the bottom of the pool.

POOL TILE:

N/A

DRAINS/SKIMMER- BASKET/ Weir(s) i.e. flap(s in view?

Drain cover;

• No drain is apparent.

Skimmer - Basket;

Satisfactory where visible

Weir /Flap(s;

No weir/flap in view

POOL SWEEPS:

• No cleaning equipment present and working at time of inspection visit.

IS AN ATTACHED SPA / UPPER POOL PRESENT? No

DIVING BOARD IF PRESENT: N/A

Page 30 of 39

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

I NI NP D

SLIDES/STEPS /LADDER:N/A

EQUIPMENT PAD:

Pad:

Satisfactory

FILTER /MEDIUM/HOUSING:

Working at time of inspection

POOL LIGHT(S)/GFCI PROTECTION:

Pool Light(s:

• Not Working at time of inspection. There may be a switch that was not readily identifiable.

PUMP(S)/MOTOR(S)/CONTROLS:

Pool Pump(s / Motor(s / Controls:

• Satisfactory / Working at time of inspection.

PLUMBING/VALVES/VISIBLE PLUMBING:

Pool's visible Plumbings / Valves;

• Notice: Water lines are not labeled 100%.

Pool Chlorination Type(s in place: Salt

• Notice: The Control board indicates Salt Levels as: Producing . Water sampling should be considered as a comparison to the panel's readings. Refer to seller concerning replacement and/or repairs performed. Most units have a life span between 4- 6 years and require periodic servicing / repairs/replacements.

Additionals:

Ozonator present?:

No

Is a SVRS Safety Vacuum Release System Present?: No

HEATER(S): Electric

Hayward

Page 31 of 39

This is a personal, private and confidential report with all rights reserved by Kissee Inspections and the client, Kristina Malone & Eddie Hemphill. This Inspection Report is issued by William Christopher Mullins TREC # 23852. Written permission must be obtained before being issued to anyone other than the buyer on page one of this report.

© 2024 Kissee Inspections

Kisseeinspections.com

469.789.1444

Report Identification: 20240911-001, 990 Harmony Cir, Nevada	, TX
	

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

• Did not respond to Direct manual controls. The unit turned on however it appear there is a need of a remote to operate the entire system.

CHILD SAFETY BARRIERS/FENCES/GATES/ENCLOSURES ALARMS:

- Not Working on a one foot swing to clasp close. Refer to NSPF and or CPSA for further information.
- Fencing /Gates No secondary child fencing was found erected / in place surrounding the pool.
- No "Working" secondary alarms on pool side doors and windows.

CHLORINATOR/ Ozonator: Chlorinator(s / ozonator(s) is/ are specialized equipment and are deferred to your pool service company and the manufacture for proper up keep & performance. Salt chlorinator typical life expectancy is four(4) to six (6) years replacement should be expected at such interval. Refer to seller(s) concerning when salt chlorinator was installed, updated, etc.

General Comments

The swimming pool is of the opinion as in need of service, as a minimum. Swimming pool inspections are confined to visual observations and do not include any item that cannot be seen. Only visible piping can be inspected for leaks. Filters are not tested for media or function. Heaters are not tested under any circumstances which may constitute harm to inspector and or real property. The interior surface of the pool is not observed for cracks unless the pool is drained at the time of the inspection. The State of Texas, Real Estate Commission (regulating-licensing agency of home inspectors) does not have jurisdiction over the inspection of swimming pools and does not adjudicate issues arising out of the inspection of same.

Notice: Recommend you monitor the pool during the summer season for a complete circulation in all areas, and to note any algae areas. This will indicate that the pool is in need of greater circulation and possible outlet port additions, *as an example*.

• Please read the entire report above.

Notices:

- Diving Boards and/or Slides; U.S. Consumer Product Safety Commission strongly recommends that all diving boards and/or slides be removed from pools for reasons of safety.
- Per Texas Real Estate Commission Standards of Practice "Full evaluation of the integrity of the pools gas heater heat exchanger requires dismantling of the furnace and is beyond the scope of a visual inspection."

"By today's standards, several safeguards would be required to prevent accidental drowning. Some of these recommendations may be safety upgrades. Recommend installing self-closing and self-latching devices on all doors/gates with direct access to the pool/spa area. These doors/gates should swing away from the pool/spa area and have release mechanisms that must be at least 54" above the floor/deck. Additionally, doors and windows of the residence which lead to and are directly adjacent of the pool/spa should have an alarm capable of providing a sound level of not less than 85 dBA. Buyer should consult a swimming pool contractor for details and additional information and requirements that apply to this residence." *Owning a pool comes with responsibility similar of owning a car. It doesn't matter how old it is... it only matters that safety rules and laws are adhered too.*

Recommend a professional pool service / repair company further inspect and repair as required / desired.

Page 32 of 39

Report Identification: 20240911-001, 990 Harmony Cir, Nevada, TX

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

The objective of our limited visual pool/spa inspection is to determine if the pool/spa and related equipment may benefit from a more thorough inspection by a qualified pool specialist. Inspection of pool and spa components are limited by the following visual inspection procedures or conditions. Advanced testing such as pressure tests, supporting soils tests, underground leak tests or disassembly of components will not/ and have not been performed as this is, and has been a visual inspection and conducted as such. Inherent defects may not be readily visible such as at the bottom of a dirty pool or a pool shell that is in stained or molted condition, and or weather conditions such as wind and/or rain clouds etc. limiting ready view to the pool underwater conditions. The inspection report is based on current condition at the time of inspection and makes no determination as to how long any component will last. We do not dismantle components. The inspection will not include testing or operation of auto-chlorinators, pool cleaning systems, filter back wash systems, solar heating performance, components beneath the water, chemical composition of the water, effectiveness of the filter, heating system sizing, drain system, testing of diving boards, proper depth for diving, underground piping or underground electrical related to the pool systems. We make no warranties, expressed or implied, relating to the present condition of the pool/spa and or equipment nor suitability for continued service. Any items not specifically addressed in the report are considered to be beyond the scope of a home inspection and are excluded.

Page 33 of 39

ADDENDUM: REPORT SUMMARY

The following is a synopsis of the potentially significant improvements that should be budgeted for over the short term. Other significant improvements, outside the scope of this inspection, may also be necessary. Please refer to the body of this report for further details on these and other recommendations.

Note: Items considered cosmetic in nature or that are due to code changes or changes to the Texas Real Estate Commissions' "Standards of Practice" since the house was built; may or may not be included in the Report Summary. Please read the entirety of the report. The following is not intended as an all inclusive item list.

ADDITIONAL INFO PROVIDED BY INSPECTOR

Recommendation for Addressing Deficiencies -Whenever a system or component of the house is marked as D=Deficient and or noted for concerns, it is the Client's responsibility to find and make arrangements for a qualified professional, or technician to further inspect, evaluate and service the ENTIRE SYSTEM prior to the end of any option or review period. Furthermore, it is the Client's responsibility to instruct any person conducting the review to take into account not only the problem or issue identified by the inspector, but also any adjacent, collateral or contiguous, intersecting and/or hidden/obstructed systems, components or issues that may require repair, replacement or upgrading. By not properly addressing deficiencies, problems or concerns through the repair amendment process, the client is accepting the condition of the property and becomes responsible for any current and or future repairs. SOMETIMES NOTED DEFICIENCIES ARE SYMPTOMS OF OTHER, MORE SERIOUS AND COSTLY, DEFECTS.

FOUNDATIONS

- Corner cracking/ popping was observed, as typical found for the area.
- Low soil back fill height noted, with the bottom portions of the slab showing. Corrections are encouraged.

GRADING AND DRAINAGE

- The soil line is low. Under current building standards there should be at least 4-inches of foundation visible below masonry veneer and 6-inches of foundation visible below wood type veneer.
- Gutter / down spout(s noted as dented / damaged.

ROOF COVERING MATERIALS

- There was no kickout flashing details observed at the lower bottom edge of the roof line interface and the sidewall that continues past the edge of the roof. The lack of this kickout flashing will allow water to penetrate at these points.
- Worn / scuffed covering noted. Refer to a roofing contractor for recommendation/ repairs/ replacement options.
- Notice: Refer to your seller for further information. Contact your insurance company & see if they will pull a CLUE report before closing to better inform concerning your future purchase. C.L.U.E. (Comprehensive Loss Underwriting Exchange) is a claims history database generated by LexisNexis® that enables insurance companies to access consumer claims information when they are underwriting or rating an insurance policy.

Page 34 of 39

ROOF STRUCTURES AND ATTICS

Insulation & Ventilation:

- Compressed insulation noted and should be rearranged, improved as deemed / desired necessary.
- What appeared as past attic Rodent tunneled/ pathway areas and packed down insulation noted. Insulation improvements are considered as in need. Consult with seller(s) concerning any past pest control efforts if performed and success if such was effective as well as any warranty if in place and conditions, etc.
- Attic is in use with storage items and is recommended to be cleared out and further inspected with any corrections, repairs performed before closing should such exists.

WALLS (INTERIOR AND EXTERIOR)

- Exterior & interior wall frames, sills, and penetrations, wall expansion joints;- glazing/caulk/grouting needs-up keep/ maintenance/ repairs. Recommend all areas to be serviced at the purchaser's &/or repair professional's discretion.
- Evidence of patching was detected of the wall(s as viewed at the front entry door area of the structure as an example, refer to seller for further details.

CEILINGS AND FLOORS

- Cracks noted with in the ceilings in various areas. *Note:* These areas appear as expansions cracks from attic heating and expanding due to heat build up in the attic space.
- Past repair, patching, etc of the ceiling noted. Refer to the seller and seller's disclosure for further information. (as note at the Multiple locations area as example.
- Nail heads were observed to be pushing through the interior finish in one or more locations.


DOORS (INTERIOR AND EXTERIOR)

- The garage service door closer hinge spring was noted as not fully closing the door on a one foot swing.
- The door to the laundry room was noted to have a large gap along the striker plate side to the point it can pass the door stop as well as rubbing at the top corner.
- One or more of the doors for the structure interior were noted to be lacking detent ball and springs.

WINDOWS

- The windows appeared to have loss of thermal seals, as noted at/ in multiple locations around the entire structure such as noted in the living areas, dining room and bedroom areas. See Pics above as examples.
- Exterior window(s sealant show separation/ age / in need of servicing/replacement/. Recommend all areas to be serviced at the purchaser's &/or repair professional's discretion.

Page 35 of 39



OTHER

- Cracked drive way/garage floor/pool deck. Recommend monitoring for movement,etc.; any further concerns are deferred to a foundation contractor or a professional engineer.
- Gate / fencing requires repairs at one or more location. Structure is noted to have a pool. Refer to "Pool" section below as well as cps / nspf for pool fencing enclosures.

BRANCH CIRCUITS, CONNECTED DEVICES, AND FIXTURES

- Lighting noted as not working at the time of the inspection as observed at/in the, various locations as examples.
- **Ground Fault outlets protections** (GFCIs) in the structures are not properly working and/ or installed (as currently required) in all areas. Example: All-Kitchen counter tops, baths, garage receptacles, All-areas with in a 6" of a wet zone (i.e. kitchen sink as an example), exterior outlets etc.

COOLING EQUIPMENT

- Comments: Refer to the seller(s / tenant(s concerning any past repairs, servicing or replacement(s that may have been performed.
- The systems appeared as older system(s. Such may require a slightly higher level of maintenance, and may be more prone to major component breakdown. Predicting the frequency or time frame for repairs on any mechanical device is virtually impossible.
- Notice: The Federal EPA has currently scheduled all use of R-22 gas to cease by the year 2020. Replacement gas for any HVAC equipment may not be available commercially. Refer to a professional HVAC company for further details.
- One or more of the AC Condensation pans noted as being rusted/ with rust. Repair /replacement should be considered. Refer to the seller(s concerning prior repairs if performed as well as any warranty which may be present and if transferable.
- Water noted in the pan.

DUCT SYSTEMS, CHASES, AND VENTS


• Notice: No <u>Jump Ducts</u> found in the home for air flow to be allowed to flow from room to hallway at one or more bedrooms. Such as when doors are closed. Refer to your engineer of records and /or your builder for further details, etc. This appears as an as built item.

PLUMBING SUPPLY, DISTRIBUTION SYSTEMS AND FIXTURES

- The plumbings appear as, and are considered of the opinion of; in need of updating for performance, corrective measures as deemed necessary, and /or desired. Examples:
- **MBR Commode-** -is loose
- Guest bathroom Tub / Shower chipped enamel noted.

Changes in performance as well as updating and or repairs should be expected of any and all plumbing.

Page 36 of 39



HYDRO-MASSAGE THERAPY EQUIPMENT

No working and accessible inspection access pane/port were found installed and available for inspecting the tub's under side and equipment change out/servicing.

• Access panel noted as sealed shut..

MECHANICAL EXHAUST VENTS AND BATHROOM HEATERS

• No exterior vent terminations found to be installed for the installed units. All exhaust fans should discharge to the building exterior. This is an "as-built" condition but Per TREC standards of practice we are required to report this condition as a deficiency.

GARAGE DOOR OPERATORS

• Safety reversing mechanism (@ approximately 5 Lbs.)- did not operate when the door[s] were obstructed as noted at both of the car door units.

DRYER EXHAUST SYSTEMS

- Cleaning of the dryer vent piping/ system is in need. / Unit found with lint build up.
- The dryer duct termination is not properly sealed on the attic side of the roof structure penetration and is allowing dryer lint to fall back into the attic area.

LANDSCAPE IRRIGATION (SPRINKLER) SYSTEMS

- One or more broken head or line as well as some Sprayer head(s) noted as leaning / not vertical and not surfacing past turf and or not retracting after operating.
- Water from the sprayers were noted as directed unto hard scape and structure, etc.
- No working rain sensor was found to be present. Under current TCEQ guide lines for irrigation/ irrigator; such are
 to have a rain sensor installed.
- A Backflow preventer was not found to be present and readily accessible.
- No Labeling provided as required under the TCEQ as pertaining to the License Name and Number for the irrigation installer. Refer to your builder / seller for further information and or the TCEQ for further details.
- Notice: No designed approved TCEQ plans were found to be available for the purchaser, inspector, etc. at the Lawn and Garden Sprinkler Systems controller location. Refer to your builder or the Texas TCEQ for further details;
 - (30 TAC §344.61 (a) An irrigator shall prepare an irrigation plan for each site where a new irrigation system will be installed. A paper or electronic copy of the irrigation plan must be on the job site at all times during the installation of the irrigation system. A drawing showing the actual installation of the system is due to each irrigation system owner after all new irrigation system installations....

Professional investigation/repairs are encouraged to conform to current requirements.

Page 37 of 39

<u>SWIMMING POOLS, SPAS, HOT TUBS, AND EQUIPMENT</u>

- Some cracking of the concrete slab on ground for the pool deck surface was observed at the time of this inspection. You are strongly encouraged to have the cause and remedy further evaluated by a qualified technician, and or pool contractor prior to close.
- Notice: Water lines are not labeled 100%.
- Notice: The Control board indicates Salt Levels as: Producing . Water sampling should be considered as a comparison to the panel's readings. Refer to seller concerning replacement and/or repairs performed. Most units have a life span between 4-6 years and require periodic servicing / repairs/ replacements.
- Not Working on a one foot swing to clasp close. Refer to NSPF and or CPSA for further information.
- Please read the entire report above.

Recommend a professional pool service / repair company further inspect and repair as required / desired.



For DYI Home Maintenance Tips / Videos Please Scan and or Click

Please read the entirety of the report. The above is not intended as an all inclusive item list.



Please note: Due diligence was performed to provide a detailed inspection of the above property. Please read the entire report. Should you have any questions or concerns please contact us.

I wish to thank you for.....
"The opportunity to serve you"...
To Your success
William Christopher Mullins
TREC23852
TPCL
NAWT
NSPF/CPI
TPREIA
ASHI
PTI







Page 39 of 39



INFORMATION ABOUT ON-SITE SEWER FACILITY

USE OF THIS FORM BY PERSONS WHO ARE NOT MEMBERS OF THE TEXAS ASSOCIATION OF REALTORS®, INC. IS NOT AUTHORIZED. © Texas Association of Realtors® Inc., 2004

CONCERNING PROPERTY AT 990 Harmony Circle, Nevada, Texas 75173					
A. DES	SCRIPTION OF ON-SITE SEWER FA	ACILITY ON PROPE	RTY:		
(1)	Type of Treatment System: □	□ Septic Tank	☑ Aerobic Treatment	□ Unl	known
(2)	Type of Distribution System:	Sprinker		_ Unl	known
(3)	Approximate Location of Drain Fig	eld or Distribution Sys	stem:	⊡ Unl	known
, ,	Backyard				
(4)	Installer	AAA Spetic		_ □ Unl	known
(5)	Approximate Age:	2007		_ □ Unl	known
B. MAI	NTENANCE INFORMATION:				
(1)	Is Seller aware of any maintenance onto the seller aware of maintenance control of the seller aware of any maintenance control of the seller aware of the seller a	ract:		□ Yes	☑ No
	(Maintenance contracts must be in standard" on-site sewer facilities.)	n effect to operate as	erobic treatment and certain '	'non-	
(2)	Approximate date any tanks were 9/29/2023	last pumped?			
(3)	Is Seller aware of any defect or m	alfunction in the on-s	site sewer facility?	□ Yes	☑ No
	n yee, explain				
(4)	Does Seller have manufacturer or	warranty information	n available for review?	□ Yes	☑ No
C. PLA	ANNING MATERIALS, PERMITS AN	ID CONTRACTS:			
(1)	☐ Planning materials ☐ Permit	for original installatio	n □ Final inspection when		installed
	☐ Maintenance contract ☐ Mar	ufacturer information	n □ Warranty information	☑ other	
(TXR 140		Buyer ,	$\mathcal{E} \mathcal{K} \qquad \mathcal{K} \mathcal{M}$ and Seller $\begin{picture}(20,20) \put(0,0){\line(1,0){100}} \put(0,0)$		Page 1 of 2

- (2) "Planning materials" are the supporting materials that describe the on-site sewer facility that are submitted to the permitting authority in order to obtain a permit to install the on-site sewer facility.
- (3) It may be necessary for a buyer to have the permit to operate an on-site sewer facility transferred to the buyer.
- D. INFORMATION FROM GOVERNMENTAL AGENCIES: Pamphlets describing on-site sewer facilities are available from the Texas Agricultural Extension Service. Information in the following table was obtained from Texas Commission on Environmental Quality (TCEQ) on 10/24/2002. The table estimates daily wastewater usage rates. Actual water usage data or other methods for calculating may be used if accurate and acceptable to TCEQ.

<u>Facility</u>	Usage (gal/day) without water- saving devices	Usage (gal/day) with water- saving devices
Single family dwelling (1–2 bedrooms; less than 1,500 sf)	225	180
Single family dwelling (3 bedrooms; less than 2,500 sf)	300	240
Single family dwelling (4 bedrooms; less than 3,500 sf)	375	300
Single family dwelling (5 bedrooms; less than 4,500 sf)	450	360
Single family dwelling (6 bedrooms; less than 5,500 sf)	525	420
Mobile home, condo, or townhouse (1-2 bedroom)	225	180
Mobile home, condo, or townhouse (each add'l bedroom)	75	60

This document is not a substitute for any inspections or warranties. This document was completed to the best of Seller's knowledge and belief on the date signed. Seller and real estate agents are not experts about on-site sewer facilities. Buyer is encouraged to have the on-site sewer facility inspected by an inspector of Buyer's choice.

Edward K Hemphill	2025-08-31	Kristina Marie Malone	2025-08-31
Signature of Seller	Date	Signature of Seller	Date
Receipt acknowledged by:			
Signature of Buyer	Date	Signature of Buyer	Date

Page 2 of 2



Eddie Hemphill <ekhooo@gmail.com>

Fwd: Empire Today: Contract Change Order Requires Your Acceptance

1 message

Kristina Malone <stranded_in_japan@hotmail.com>
To: Eddie Hemphill <ekhooo@gmail.com>

Tue, Oct 8, 2024 at 11:07 PM

Sent from my iPhone

Begin forwarded message:

From: do-not-reply@empiredocuments.com
Date: October 7, 2024 at 10:21:09 AM CDT
To: stranded in japan@hotmail.com

Subject: Empire Today: Contract Change Order Requires Your Acceptance



You're receiving this message because your contract was recently changed and requires your acceptance of this Change Order as detailed below.

Please review and accept the revised contract detail below.

By clicking Accept Change below, I agree to amend and modify Contract # 015TADH676 as set forth below, and affix my electronic or digital signature with the same effect as if I signed this Change Order in ink on paper binding me and Empire Today, LLC to the below changes incorporated into the Contract as if fully set forth therein, all other terms and conditions of which I ratify and reaffirm.



Contract Number: 015TADH676


Customer Name: Kristina Malone

Contract Total: \$4,399.00

Installation Date: Wednesday, October 9, 2024


Carpet SO02418182

Bedroom 3




Padding Vegas Plus 8lb 1/2" w/ Barrier	
Embossing Leveler	No
Take Up	Take Up Carpet Over Pad
Haul Away	Yes
Spotlight	Limelight
Closet	
	Product: Spotlight - Limelight
Embossing Leveler	No
Take Up	Take Up Carpet Over Pad
Haul Away	Yes
Padding	Vegas Plus 8lb 1/2" w/ Barrier
Spotlight	Limelight
Installation Method	Tackless - Texture

Bedroom 2



Installation Method Tackless - Texture	
Padding	Vegas Plus 8lb 1/2" w/ Barrier
Haul Away	Yes
Take Up	Take Up Carpet Over Pad
Embossing Leveler	No
Master Bedroom	
	Product: Spotlight - Limelight
Take Up	Take Up Carpet Over Pad
Embossing Leveler	No
Haul Away	Yes
Spotlight	Limelight
Installation Method	Tackless - Texture
Padding	Vegas Plus 8lb 1/2" w/ Barrier

Bedroom



Please review and accept the revised contract detail below.

By clicking Accept Change below, I agree to amend and modify Contract # **015TADH676** as set forth above, and affix my electronic or digital signature with the same effect as if I signed this Change Order in ink on paper binding me and Empire Today, LLC to the above changes incorporated into the Contract as if fully set forth therein, all other terms and conditions of which I ratify and reaffirm.



Please contact us at 866-588-0124 with any questions regarding your contract.

1205 Post & Paddock, Grand Prairie, TX 75050



Eddie Hemphill <ekhooo@gmail.com>

Transaction Receipt from VETERAN GARAGE DOORS for \$1242.60 (USD)

1 message

Auto-Receipt <noreply@mail.authorize.net> Reply-To: Office Charge CC <office@vetgd.com>

To: Edward Hemphill <ekhooo@gmail.com>

Wed, Oct 16, 2024 at 4:50 PM

Veteran Garage Door www.veterangaragedoor.com 972.885.2982 817.769.6674

Order Information

Description: Goods or Services

Customer ID a2VVJ000000JylF2AS Tax Exempt No

Billing Information

Shipping Information

Edward Hemphill 990 Harmony Circle Nevada, TX 75173

US

ekhooo@gmail.com

Shipping: \$0.00 (USD)

Total: \$1242.60 (USD)

Payment Information

Date/Time: 16-Oct-2024 16:50:08 CDT

Transaction ID: 120704688583 Payment Method: Visa xxxx3734 Transaction Type: Purchase 398375 Auth Code:

Merchant Contact Information

VETERAN GARAGE DOORS GRAND PRAIRIE, TX 75050

US

office@vetgd.com Office@vetgd.com

Honest Water Co Work Order - Proposal - Agreement

First NameEdward	_ Last NameHemphill
Phone 2145514223	Email ekhooo@gmail.com
Full Address 990 Harmony Cir. Nevada, TX 75173 Hencet Water Co Will furnish all products, meterial and lab	hor to install the following. The Durchesor(s) hereby order and nurshase
•	bor to install the following. The Purchaser(s) hereby order and purchase or and installation of the following:
Hydro Spring Whole Home Water Filtration and Softener System	
Intelliclear 600 with Aklaine Filter and Oil Rubbed Bronze Faucet	
Bury job - Installer will look for alternatives first	
Installation Date: 11/09/2024	
Arrival Window: 10:00 am to 12:00 pm	
Sales Price \$2950	
The placement of the Water Treatment Equipment is to be de-	tion Instructions etermined by Honest Water Co, installation crew, and Purchaser(s), as to e best location.
Upon signing, you acknowledge that you agree to the terms Credit, Debit, or Finance. Failure to pay within 48 Ho	nt Method/Terms as of this agreement. Upon installation, you must pay via Cash, Check, ours of Installation will result in a \$50 charge. All sales are final. ge. Debit Card Transactions will result in Zero Additional Costs.
	Warranty
-	st, leak, corrode, burst, or in any other manner fail to perform proper functions.
Honest Water Co Insures a Lifetime Warranty on all parts in	nvolved in the whole home water treatment system. The customer will
For the LIFETIME of the Media, the MEDIA BED is guar	nt hardware for the Whole Home System. aranteed to be free of defects in materials and workmanship to reduce
For the first 12 months after installation, Honest Water Co ins	ine, as well as produce soft water. Issures a full labor warranty. Service Calls after 12 months will result in a dent on the customer location.
Purchaser Edward He	emphill Date 11/05/2024
RepresentativeScott I	Meyer Date Date

Signature Certificate

Reference number: 4JW4G-8GB2P-98Z9P-ZXVXP

Signer Timestamp Signature

Scott Meyer

Email: scott@honestwaterco.com

 Sent:
 05 Nov 2024 17:49:24 UTC

 Viewed:
 05 Nov 2024 17:49:27 UTC

 Signed:
 05 Nov 2024 17:57:33 UTC

Recipient Verification:

✓ Email verified 05 Nov 2024 17:49:27 UTC

IP address: 65.36.89.8

Scott Meyer

Location: Little Elm, United States

Edward Hemphill

Email: ekhooo@gmail.com

 Sent:
 05 Nov 2024 17:49:24 UTC

 Viewed:
 05 Nov 2024 19:58:50 UTC

 Signed:
 05 Nov 2024 19:59:23 UTC

Recipient Verification:

✓Email verified 05 Nov 2024 19:58:50 UTC

Edward Hemphill

IP address: 47.186.125.39 Location: Wylie, United States

Document completed by all parties on:

05 Nov 2024 19:59:23 UTC

Page 1 of 1



Signed with PandaDoc

PandaDoc is a document workflow and certified eSignature solution trusted by 50,000+ companies worldwide.





Master Plumbing License - Brad Bacon

#M-37346

Plumbing Regulated by:

Texas State Board of Plumbing Examiners

929 East 41st Street Austin, Texas 78751 1-(800) 845-6584

https://tsbpe.texas.gov

HVAC License -

TDLR - #TACLA87530C HVAC Regulated by:

The Texas Department of Licensing and

Regulation P.O. Box 12157 Austin Texas 78711 1-(800)-803-9202 **Electrical Master License - #199130**

Texas Department of Licensing and

Regulation

Electricians Program P.O. Box 12157 Austin Texas 78711 1-(800)-803-9202

CUSTOMER:

Hemphill, Edward 1703 Westbury Drive Rockwall, TX 75032 USA Job Location: Hemphill, Edwards 990 Harmony Circle Nevada, TX 75173 USA

Invoice 158601682 Invoice Date 10/18/2024

DESCRIPTION OF WORK

Mr. Edwards had us come out today to give him some options on replacing his 5 ton heat pump. This system is original to the house it is from 2007 and it is on the absolute refrigerant which is the R 22. The unit upstairs in the attic, which is the air handler which helps blow air throughout. The house is completely rusted out and corroded. The build of the equipment itself is actually falling apart as well as the drain pan. There is not enough return air on the system, which can cause the system to run well below standards pay higher utility bills month and month out. The good news is, I went through the entire system, including the ductwork and put together some great options that not only will install a new system, but also lower utility bills and have the latest and greatest bills and whistles to go along with monitor and Everything.

Complete and collected 🚧 Install notes 🚧

- / from straight electric 3ton to 3.5ton heat pump
- Thermostat wire is count of 6 now
- Nest thermostat
- Configurated for heat pump
- we are adding a return in the office room with the computers 10" duct rung
- there are two supply's coming off the plenum that we are changing
- 7" that feeds a 6" and 5" it's not correct we need upsize the 7" to a 8"
- 10" that feeds two 6" and two 5" we are upsizing it from a 10" to a 12"
- No condenser pad as both units are on a concrete slab
- Please make sure you are taking out the right system

Heat Pump Air Handler

- 2007 Carrier straight cool

TASK	DESCRIPTION	QTY	PRICE	TOTAL
L0-HP- 215213860	Bacon 3.5 Ton Heat Pump Complete System L0-HP-210318473	1.00	\$12,050.23	\$12,050.23

Thermal Expansion Valve Standard Thermostat

4" Media Air Filter Rack

(1) Media Filters New equipment pad

New equipment mounting system for indoor (Hungrite)

New electrical disconnect & whip

New Emergency Drain Pan

All connections

Float Switch

Flue pipe Connections to existing Flue

Reconnect to existing ductwork

Basic Drain Package

Initial Programming of Thermostat

Mastic Seal System for Air Loss

New Sheet Metal Duct Plenums

New Armaflex with UV wrap outdoor

Locking Refrigerant Caps

Labor and Permit Fees Included

Warranty Description

10 Year BACON WRAPPED Parts

5 Year BACON WRAPPED Labor

10 Year Compressor Lifetime Heat Exchanger

T601065	Includes New Duct, Boot and Grill from plenum to outlet.	1.00	\$1,168.53	\$1,168.53
T604367	Duct Replacement	2.00	\$645.69	\$1,291.38
	Add Qty for additional runs			
HVACPERMIT	01HVAC Permit	1.00	\$0.00	\$0.00
	Due to local licensing and permit requirements, a permit will need to be ta to perform the services we quoted.	ken out		
		SUB-TOTAL		\$14,510.14
		TOTAL DUE	5	\$14,510.14
		PAYMENT	;	\$14,510.14
		BALANCE DUE		\$0.00

Thank You for being a valued customer! If you should ever have any issues, please contact us at 972-722-4006. http://www.everyonelovesbacon.com



Eddie Hemphill <ekhooo@gmail.com>

Invoice 3052 due from Year Round Septic Services - \$750.00

1 message

Year Round Septic Services <notifications@housecallpro.com>
Reply-To: Year Round Septic Services <yearroundseptic@gmail.com>
To: Ekhooo@gmail.com

Sat, May 10, 2025 at 3:02 PM



Your invoice from Year Round Septic Services

Pay as low as \$34.23/mo*

Complete a short application to buy now and pay over time.

APPLY NOW

Hi Edward,

Thank you for choosing Year Round Septic Services. Please see attached invoice due upon receipt.

Invoice Number: #3052

Service Date: May 08, 2025

Customer Name: Edward Hemphill

Service Address: 990 Harmony Circle, Nevada, TX 75173

Materials	qty	unit price	amount
Install new air compressor	1.0	\$750.00	\$750.00
Subtotal			\$750.00
Total job price			\$750.00

Amount Due \$750.00

Pay online

(469) 512-9149 | yearroundseptic@gmail.com

http://Yearroundseptic.com

1613 Bozman Rd, Wylie TX 75098, Wylie, TX 75098

Terms & Conditions



Codefied Inc.

4180 Wynkoop Street, Suite 310, Denver, CO 80216

By using Housecall Pro services, you agree to the Housecall Pro Terms of Service

Help Center

