

8203-98th Street Fort St. John, BC V1J 6W5 250-785-6829

April 30, 2021

LOCATION: 9819 102nd Avenue Units #104 & 203

This letter is to confirm that Conway Electric Inc. has inspected the electrical system at the above noted address on April 30, 2021. I confirm that the electrical equipment and wiring is in good working condition with no signs of damage. The electrical panels in all the suites are breaker type. All wiring is copper, there is no knob and tube or aluminum wiring present.

There are no repairs needed at this time. In my opinion, the electrical panels and wiring are in safe and satisfactory condition.

Regards,

Mike Conway

Conway Electric Inc.



8203-98th Street Fort St. John, BC V1J 6W5 250-785-6829

April 30, 2021

LOCATION: 9820 102nd Avenue Units #202 & 304

This letter is to confirm that Conway Electric Inc. has inspected the electrical system at the above noted address on April 30, 2021. I confirm that the electrical equipment and wiring is in good working condition with no signs of damage. The electrical panels in all the suites are breaker type. All wiring is copper, there is no knob and tube or aluminum wiring present.

There are no repairs needed at this time. In my opinion, the electrical panels and wiring are in safe and satisfactory condition.

Regards,

Mike Conway

Conway Electric Inc.